

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402024570
Date Received:
04/29/2019

FIR RESOLUTION FORM

CA Summary:
1 of 1 CAs from the FIR responded to on this Form
0 CA Completed
1 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-3779
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name Phone Email
Luke Reddy 970-515-1292 luke.reddy@anadarko.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 674902808
Inspection Date: 04/24/2019 FIR Submit Date: 04/26/2019 FIR Status:

Inspected Operator Information:

Company Name: KERR MCGEE OIL & GAS ONSHORE LP Company Number: 47120
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-3779

LOCATION - Location ID: 463802

Location Name: BARCLAY FARMS Number: 37-28HZ PAD County:
Qtrqtr: NENE Sec: 28 Twp: 3N Range: 66W Meridian: 6
Latitude: 40.202398 Longitude: -104.776379

FACILITY - API Number: 05-123-00 Facility ID: 463802

Facility Name: BARCLAY FARMS Number: 37-28HZ PAD
Qtrqtr: NENE Sec: 28 Twp: 3N Range: 66W Meridian: 6
Latitude: 40.202398 Longitude: -104.776379

CORRECTIVE ACTIIONS:

1 CA# 124624

Corrective Action: Install, repair, or replace required BMPs per Rule 1002.f. in accordance with good engineering practices. Date: 04/25/2019

Response: FACTUAL REVIEW REQUEST

Basis for Review: Corrective action dates are not attainable

Operator Comment: BMP's have not been installed and completed because inspection was done two days after construction began. BMP's were in process of being installed during inspection and ditch and berms were in process of being cut and built during the inspection.

The corrective action date was set for 4/25 and the inspection was not submitted until 4/26. A corrective action date in the past is not attainable.

All required stormwater BMP's will be installed on location but it takes longer than two days.

COGCC Decision: **Not Approved**

COGCC Representative: Operator shall install stormwater and erosion control BMPs prior to the start of construction in accordance with good engineering practices.

COGCC Supervisor: Operator shall install stormwater and erosion control BMPs prior to the start of construction in accordance with good engineering practices.

OPERATOR COMMENT AND SUBMITTAL

Comment: BMP's have not been installed and completed because inspection was done two days after construction began. BMP's were in process of being installed during inspection and ditch and berms were in process of being cut and built during the inspection.
The corrective action date was set for 4/25 and the inspection was not submitted until 4/26. A corrective action date in the past is not attainable.
All required stormwater BMP's will be installed on location but it takes longer than two days.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Luke Reddy

Signed: _____

Title: Regulatory Specialist

Date: 4/29/2019 10:41:42 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402024570	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files