

HILL RANCH 29-14 API# 05-071-06261 & HILL RANCH 29-14V API# 05-071-07553– TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 28, 2019  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401849



PHOTO 1: THE IMPACTED SOIL AROUND THE WELL HEAD WAS REMOVED FROM THE LOCATION.

HILL RANCH 29-14 API# 05-071-06261 & HILL RANCH 29-14V API# 05-071-07553– TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 28, 2019  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401849



PHOTO 2: THE RISER WAS MARKED.

HILL RANCH 29-14 API# 05-071-06261 & HILL RANCH 29-14V API# 05-071-07553– TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 28, 2019  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401849



PHOTO 3: THE RISER WAS MARKED.

HILL RANCH 29-14 API# 05-071-06261 & HILL RANCH 29-14V API# 05-071-07553– TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 28, 2019  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401849



PHOTO 4: THIS IS AN ELECTRICAL BOX AND NOT A PIPELINE RISER, BUT WAS LABELED AS SUCH.

HILL RANCH 29-14 API# 05-071-06261 & HILL RANCH 29-14V API# 05-071-07553– TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 28, 2019  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401849



PHOTO 5: THE UNUSED EQUIPMENT WAS REMOVED FROM THE LOCATION. THE STEP THAT IS USED TO GAUGE THE TANK WAS LEFT INPLACE.

HILL RANCH 29-14 API# 05-071-06261 & HILL RANCH 29-14V API# 05-071-07553– TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 28, 2019  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401849



PHOTO 6: THE DIRT BERM WAS DOMINATED.

HILL RANCH 29-14 API# 05-071-06261 & HILL RANCH 29-14V API# 05-071-07553– TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 28, 2019  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401849



PHOTO 7: THE UNUSED EQUIPMENT WAS REMOVED. THE LOADING POD LIDS THAT BLEW OFF IN THE WIND WERE PLACED BACK ON THE LOADING PODS.

HILL RANCH 29-14 API# 05-071-06261 & HILL RANCH 29-14V API# 05-071-07553– TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 28, 2019  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401849



PHOTO 8: THE LOADING POD LIDS THAT BLEW OFF IN THE WIND WERE PLACED BACK ON THE LOADING PODS.