

APACHE CANYON 29-06 API# 05-071-09288 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 12, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401839



PHOTO 1: REPLACED THE PACKING TO ELIMINATE THE WATER LEAK. PACKINGS WERE SECURELY FASTENED.

APACHE CANYON 29-06 API# 05-071-09288 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 28, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401839



PHOTO 2: THE STAINED SOIL BEHIND THE SEPARATOR HOUSE WAS CLEANED UP.

APACHE CANYON 29-06 API# 05-071-09288 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 28, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401839



PHOTO 3: THE STAINED SOIL AROUND THE ENGINE SKID WAS CLEANED UP.

APACHE CANYON 29-06 API# 05-071-09288 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 28, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401839



PHOTO 4: THE STAINED SOIL AROUND THE ENGINE SKID WAS CLEANED UP.