

APACHE CANYON 29-04 API# 05-071-09281 – TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 - DATE: MAY 02, 2019  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401841



PHOTO 1: THE IMPACTED SOIL AROUND THE LIQUID RING COMPRESSOR WAS REMOVED FROM THE LOCATION.

APACHE CANYON 29-04 API# 05-071-09281 – TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 - DATE: MAY 02, 2019  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401841



PHOTO 2: THE IMPACTED SOIL AROUND THE LIQUID RING COMPRESSOR WAS REMOVED FROM THE LOCATION.

APACHE CANYON 29-04 API# 05-071-09281 – TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 - DATE: MAY 02, 2019  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401841



PHOTO 3: THE IMPACTED SOIL NEXT TO THE ENGINE SKID WAS REMOVED FROM THE LOCATION. THE UNUSED BOARDS WERE ALSO REMOVED FROM THE LOCATION.

PHOTO 4: THE IMPACTED SOIL NEXT TO THE ENGINE SKID WAS REMOVED FROM THE LOCATION.

PHOTO 5: THE UNUSED EQUIPMENT WAS REMOVED FROM THE LOCATION.