

APACHE CANYON 26-16V API# 05-071-07558 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: MAY 06, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695100497



PHOTO 1: THE IMPACTED SOIL AROUND THE LIQUID RING COMPRESSOR WAS REMOVED FROM THE LOCATION.

APACHE CANYON 26-16V API# 05-071-07558 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: MAY 06, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695100497



PHOTO 2: THE IMPACTED SOIL NEXT TO THE ENGINE SKID WAS REMOVED FROM THE LOCATION.

APACHE CANYON 26-16V API# 05-071-07558 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: MAY 06, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695100497



PHOTO 3: THE OIL ACCUMULATION IN THE CONTAINMENT WAS REMOVED.

APACHE CANYON 26-16V API# 05-071-07558 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: MAY 06, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695100497



PHOTO 4: THE IMPACTED SOIL NEXT TO THE ENGINE SKID WAS REMOVED FROM THE LOCATION.