

APACHE CANYON 26-01 API# 05-071-06134 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: MAY 06, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695100485



PHOTO 1: THE FLUID ACCUMULATION ON THE SKID WAS REMOVED. THE IMPACTED SOIL AROUND THE LIQUID RING COMPRESSOR WAS REMOVED FROM THE LOCATION. ALL VALVES AND FITTINGS WERE SECURELY FASTENED.

APACHE CANYON 26-01 API# 05-071-06134 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: MAY 06, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695100485



PHOTO 2:THE FLUID ACCUMULATION ON THE SKID WAS REMOVED AND THE SKID WAS CLEANED.

APACHE CANYON 26-01 API# 05-071-06134 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: MAY 06, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695100485




PHOTO 3: A RED POST WAS INSTALLED TO MARK THE TWO FOOT FREEBOARD LEVEL IN THE PIT.