

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402030947

Date Received:
05/13/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

5 of 5 CAs from the FIR responded to on this Form

5 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10661

Name of Operator: BISON OIL & GAS II LLC

Address: 518 17TH STREET #1800

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Abigail Wenk</u>	<u>7206446997</u>	<u>awenk@bisonog.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 682504584

Inspection Date: 03/08/2019

FIR Submit Date: 03/12/2019

FIR Status: _____

Inspected Operator Information:

Company Name: BISON OIL & GAS II LLC

Company Number: 10661

Address: 518 17TH STREET #1800

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 454166

Location Name: Hunt 8-60 Number: 6C County: _____

Qtrqr: Lot 7 Sec: 6 Twp: 8N Range: 60W Meridian: 6

Latitude: 40.687550 Longitude: -104.141661

FACILITY - API Number: 05-123-00 Facility ID: 454166

Facility Name: Hunt 8-60 Number: 6C

Qtrqr: Lot 7 Sec: 6 Twp: 8N Range: 60W Meridian: 6

Latitude: 40.687550 Longitude: -104.141661

CORRECTIVE ACTIONS:

1 CA# 123164

Corrective Action: Install or repair BMPs to prevent pollutant discharge from contaminated soil stockpile by 3/15/2019

Date: 03/15/2019

Response: CA COMPLETED

Date of Completion: 03/14/2019

Operator Comment: Contaminated soil was removed from the location.

COGCC Decision: _____

COGCC
Representative:

2 CA# 123167

Corrective Action: Conduct weed management and comply with Rule 1002.c.

Date: 04/12/2019

Response: CA COMPLETED

Date of Completion: 04/17/2019

Operator Comment: Work delayed due to weather and muddy pad conditions. Extension request submitted to COGCC in follow up sundry but was denied.
Weed management will be ongoing.

COGCC Decision: _____

COGCC
Representative:

3 CA# 123168

Corrective Action: Install and repair stormwater and erosion control BMPs in accordance with good engineering practices and 1002.f by 4/12/2019

Date: 03/26/2019

If the Operator believes sufficient BMPs have been installed, then provide calculations from the site specific stormwater plan demonstrating that the installed BMPs are sufficient to prevent sediment laden storm runoff from leaving the location.

If the operator determines that the current BMPs are insufficient, provide a site specific stormwater plan with specifications for controls that will be installed in order to bring location into compliance with Rule 1002.f(2).

Operator will be required to submit the stormwater plan via a Form 4 by 3/26/2019.

Response: CA COMPLETED

Date of Completion: 04/19/2019

Operator Comment: Work delayed due to weather and muddy pad conditions. Extension request submitted to COGCC in follow up sundry but was denied.
Stormwater and erosion control will be an ongoing effort.

COGCC Decision: _____

COGCC
Representative:

4 CA# 123234

Corrective Action: Comply with 603.f and 1002.f(2).b and place materials into secondary containment, or remove and properly store.

Date: 03/26/2019

Response: CA COMPLETED

Date of Completion: 03/14/2019

Operator Comment: See attached pictures - various containers were moved into secondary containment.

COGCC Decision: _____

COGCC
Representative:

5 CA# 123235

Corrective Action: Comply with Rule 603.f .

Date: 04/12/2019

Response: CA COMPLETED

Date of Completion: 03/14/2019

Operator Comment: Various trash and debris was removed from the location.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ariana Solis

Signed: _____

Title: Regulatory Analyst

Date: 5/13/2019 3:29:04 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
402041998	Photo
402041999	Photo

Total Attach: 2 Files