

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/14/2019

Submitted Date:

05/14/2019

Document Number:

688402166**FIELD INSPECTION FORM**

Loc ID 456747 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10459Name of Operator: EXTRACTION OIL & GAS INCAddress: 370 17TH STREET SUITE 5300City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Carlisle, J	970-534-6006	COGCCInspections@extracti onog.com	ALL INSPECTIONS
Adamczyk, Megan		megan.adamczyk@state.co.u s	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
456752	WELL	DG	03/24/2019		014-20772	Interchange B N35-20-5C	DG

General Comment:

Inspected Facilities

Facility ID: 456752 Type: WELL API Number: 014-20772 Status: DG Insp. Status: DG

Complaint

Comment: Field Inspector Assigned: Randy Silver

Complaint Received

Date: 05-12-2019

Complaint Contacted:

Date: 05-14-2019 Time: 7:30AM via phone left voice mail

Facility ID #: 456747

Inspection Document # 688402156

Nature of Complaint: odor

Field Inspector Actions:

On 05-13-2019, I was contacted by COGCC staff about a complaint received by the COGCC in reference to Odor. The complainant stated the issues were occurring outside of his home, from the Interchange A&B pad.

On 05-14-2019, I attempted to make contact with the complaint who stated on his complaint that on 5-12-19 at approximately 9:10 in the morning there was a continuous smell of motor oil until the wind shifted. The motor oil could be smelled when there was a slight breeze from the east. I performed a complete site inspection of the oil and gas location and associated wells in the area. At time of inspection, I talked with Extraction drilling supervisor he stated at time of complaint they were drilling and no unusual activity was taking place. We also spoke about adjusting odorant being used in drill cuttings. At time of inspection, I did not smell any unusual odors. I spoke with Broomfield inspectors and they are aware of complaint and have responded to it.

See inspection document #688402156 per my inspection.

All information reviewed and site inspection information were submitted to the COGCC for further review.

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
Inspection due to complaint see Doc#688402156 for full inspection.	silverr	05/14/2019