

Inspection Photos

5/14/2019

Operator: PCR OPERATING LLC - 10657

Location ID: 454154

Inspection Doc. Number: 696200047

Morgan County, CO

Aaron Trujillo

NE Reclamation Specialist

COGCC

Inspection Photos
Operator Name: PCR OPERATING LLC - 10657
Location ID: 454154



Photo 1: Photo taken from the south end of the drill pit, facing north. Contractor was on site at time of inspection removing material from pit. Photo shows work in process.

Inspection Photos
Operator Name: PCR OPERATING LLC - 10657
Location ID: 454154



Photo 2: Continued from photo 1.

Inspection Photos
Operator Name: PCR OPERATING LLC - 10657
Location ID: 454154



Photo 3: Photo taken from the well, facing west. Previous inspection documented a fluid spill at the wellhead. Operator was provided a 24 hour notices to control/contain fluid spill and clean up stained soils in accordance with 906.a. Photo shows stained soils appear to have been removed, however, Operator has failed to control/contain the fluid spill at the well head. Fluids were observed actively discharging from the pump rod contaminating approximately a 5 ft. x 6 ft. area at the well head.

Inspection Photos
Operator Name: PCR OPERATING LLC - 10657
Location ID: 454154



Photo 4: Continued from photo 3. Photo shows fluids observed discharging from the pump rod have re-contaminating approximately a 5 ft. x 6 ft. area at the well head. 6 foot measuring stick for reference.

Inspection Photos
Operator Name: PCR OPERATING LLC - 10657
Location ID: 454154



Photo 5: Continued from photo 3. Photo shows fluids observed discharging from the pump rod have re-contaminating approximately a 5 ft. x 6 ft. area at the well head. 6 foot measuring stick for reference.