

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402049229

Date Received:

05/21/2019

Spill report taken by:

Spill/Release Point ID:

SPILL/RELEASE REPORT (INITIAL /w SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to COGCC Rule 906.b. for reporting requirements of spills or releases of E&P Waste or produced fluids. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

OPERATOR INFORMATION

Name of Operator: <u>TIMBER CREEK OPERATING LLC</u>	Operator No: <u>10672</u>	Phone Numbers
Address: <u>1001 17TH STREET #1000</u>		Phone: <u>(719) 8452100</u>
City: <u>DENVER</u>	State: <u>CO</u>	Mobile: <u>(719) 8594896</u>
Zip: <u>80202</u>		Email: <u>ronaldmack@tcenergyllc.com</u>
Contact Person: <u>Ronnie Mack</u>		

INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 402049229

Initial Report Date: 05/20/2019 Date of Discovery: 05/20/2019 Spill Type: Recent Spill

Spill/Release Point Location:

Location of Spill/Release: QTRQTR NE/SE SEC 5 TWP 34S RNG 67W MERIDIAN 6

Latitude: 37.111550 Longitude: -104.902986

Municipality (if within municipal boundaries): _____ County: LAS ANIMAS

Reference Location:

Facility Type: OTHER

☐ Facility/Location ID No _____

Spill/Release Point Name: _____

☐ No Existing Facility or Location ID No.

Number: _____

☒ Well API No. (Only if the reference facility is well) 05-071-09127

Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? Yes

Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.

Were Five (5) barrels or more spilled? Yes

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): 0

Estimated Condensate Spill Volume(bbl): 0

Estimated Flow Back Fluid Spill Volume(bbl): 0

Estimated Produced Water Spill Volume(bbl): >=5 and <100

Estimated Other E&P Waste Spill Volume(bbl): 0

Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: 20.54 BBL Produced Water

Land Use:

Current Land Use: NON-CROP LAND

Other(Specify): _____

Weather Condition: Partly Sunny

Surface Owner: STATE

Other(Specify): Colorado

Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State ☐ Residence/Occupied Structure ☐ Livestock ☐ Public Byway ☐ Surface Water Supply Area ☐

As defined in COGCC 100-Series Rules

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

A Timber Creek Environmental Technician arrived on location and saw that the production pit was full and over flowing. The well feeding the pit was immediately taken out of service. The spill did leave location and no water was recovered. The spill did not reach waters of the state.

List Agencies and Other Parties Notified:

OTHER NOTIFICATIONS

Date	Agency/Party	Contact	Phone	Response
5/20/2019	COGCC	Jaso Kosola	719-641-0291	verbal @ 12:58 p.m., e-mail @ 1:12 p.m.
5/20/2019	Las Animas County	Robert Lucero	719-680-5100	verbal @ 1:02 p.m., e-mail @ 1:12 p.m.
5/20/2019	DOW	Bob Holder	719-680-1410	Left Mesage @ 1:03 p.m., e-mail @ 1:12 p.m.
5/20/2019	DOW	Dylan Thomsen	719-792-2232	Verbal @ 1:05 p.m., e-mail @ 1:12 p.m.

Was there a Grade 1 Gas Leak associated with this E & P waste spill or release? Yes ☐ No ☒

If YES, enter the Document Number of the Initial Grade 1 Gas Leak Report Form 44: _____

Was there a reportable accident associated with this E & P waste spill or release? Yes ☐ No ☒

If YES, enter the Document Number of the Initial Accident Report, Form 22: _____

SPILL/RELEASE DETAIL REPORTS

#1	Supplemental Report Date: 05/20/2019		
FLUIDS	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL	0	0	<input type="checkbox"/>
CONDENSATE	0	0	<input type="checkbox"/>
PRODUCED WATER	20	0	<input type="checkbox"/>
DRILLING FLUID	0	0	<input type="checkbox"/>
FLOW BACK FLUID	0	0	<input type="checkbox"/>
OTHER E&P WASTE	0	0	<input type="checkbox"/>
specify: _____			
Was spill/release completely contained within berms or secondary containment? NO Was an Emergency Pit constructed? NO			
Secondary containment, including walls & floor regardless of construction material , must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.			
A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit			
Impacted Media (Check all that apply) <input checked="" type="checkbox"/> Soil <input type="checkbox"/> Groundwater <input type="checkbox"/> Surface Water <input type="checkbox"/> Dry Drainage Feature			
Surface Area Impacted: Length of Impact (feet): 125		Width of Impact (feet): 8	
Depth of Impact (feet BGS): _____		Depth of Impact (inches BGS): _____	
How was extent determined?			
GPS, Visual Verification, Physical Measurement			
Soil/Geology Description:			
Non-Crp Land: Saruche / Rombo			

Depth to Groundwater (feet BGS) 250 Number Water Wells within 1/2 mile radius: 1
If less than 1 mile, distance in feet to nearest Water Well 1400 None ☐ Surface Water 300 None ☐
Wetlands 300 None ☐ Springs None ☒
Livestock None ☒ Occupied Building None ☒

Additional Spill Details Not Provided Above:

CORRECTIVE ACTIONS

#1 Supplemental Report Date: 05/20/2019

Cause of Spill (Check all that apply) ☒ Human Error ☐ Equipment Failure ☐ Historical-Unknown
☐ Other (specify)

Describe Incident & Root Cause (include specific equipment and point of failure)

A new lease operator had the Apache Canyon 5-11 valved wrong going to the Apache Canyon 5-09V instead of discharging to Outfall.

Describe measures taken to prevent the problem(s) from reoccurring:

A Timber Creek Manager will follow up on training new lease operators. Release them only when they are competent in thier duties before working on there own.

Volume of Soil Excavated (cubic yards): 0

Disposition of Excavated Soil (attach documentation) ☐ Offsite Disposal ☐ Onsite Treatment
☐ Other (specify)

Volume of Impacted Ground Water Removed (bbls): 0

Volume of Impacted Surface Water Removed (bbls): 0

REQUEST FOR CLOSURE

Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.

Basis for Closure: ☒ Corrective Actions Completed (documentation attached)

☐ Work proceeding under an approved Form 27

Form 27 Remediation Project No:

OPERATOR COMMENTS:

Timber Creek Energy is requesting closure of this spill. No soil samples were taken from this location. It has been found that soil sampling no longer adds usefull data on maller limited spills as land uses and the environment are not sensitive to short-term exposure to CBM produced water. Soil Chemistry effects from limited CBM produced water spills are temporary and shallow for several reasons: The Raton Basin is a dry gas operation; there is no crude oil or liquid hydrocarbons in the water; the TDS is normally less than 5000 mg/L; it is suitable for water source for livestock and wildlife; and in many cases approved for surface sischarge. Representative water quality results are attached for outfall 032A-A. The insitu ph is 8.4 for the attached analytical results.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Print Name: Ronnie Mack

Title: Superintendent Date: 05/21/2019 Email: ronaldmack@tcenergyllc.com

COA Type

Description

--	--

Attachment Check List

<u>Att Doc Num</u>	<u>Name</u>
402049476	ANALYTICAL RESULTS
402049479	ANALYTICAL RESULTS
402049481	ANALYTICAL RESULTS
402050558	TOPOGRAPHIC MAP

Total Attach: 4 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)