

Inspection Photos

5/20/2019

Operator: PCR OPERATING LLC - 10657

Location ID: 454154

Inspection Doc. Number: 696200076

Morgan County, CO

Aaron Trujillo

NE Reclamation Specialist

COGCC



Inspection Photos
Operator Name: PCR OPERATING LLC - 10657
Location ID: 454154



Photo 1: Photo taken from the well location, facing north. Photo shows operator has stopped the fluid discharge from the well, and appears to have cleaned the stained soils.

Inspection Photos
Operator Name: PCR OPERATING LLC - 10657
Location ID: 454154



Photo 2: Photo taken from the north end of the location, north. Photo shows operator appears to have closed the drilling pit.

Inspection Photos
Operator Name: PCR OPERATING LLC - 10657
Location ID: 454154



Photo 3: Photo taken from the south end of the location, facing west. Photos 3-6 provide an overview of the location from west, northwest, northeast to east. Photos show operator appears to have replaced the segregated soils/topsoil over the location.

Inspection Photos
Operator Name: PCR OPERATING LLC - 10657
Location ID: 454154



Photo 4: See comments under photo 3.

Inspection Photos
Operator Name: PCR OPERATING LLC - 10657
Location ID: 454154



Photo 5: See comments under photo 3.



Inspection Photos
Operator Name: PCR OPERATING LLC - 10657
Location ID: 454154



Photo 6: See comments under photo 3.

Inspection Photos
Operator Name: PCR OPERATING LLC - 10657
Location ID: 454154



Photo 7: Photo taken from the interim areas of the location. Photo shows reclamation specialist tested the interim areas for compaction. Compaction zones were discovered directly under the recently replaced topsoil; Unable to find evidence that compaction alleviation has been conducted in accordance with 1003.c

Inspection Photos
Operator Name: PCR OPERATING LLC - 10657
Location ID: 454154



Photo 8: Continued from photo 7. Photo shows “Platy” soil structures. These structures are thin, flat plates of soil that lie horizontally and are usually found in compacted soils. Unable to find evidence that compaction alleviation has been conducted in accordance with 1003.c

