

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402049705

Date Received:
05/23/2019

FIR RESOLUTION FORM

Overall Status: BOTH

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

1 CA Completed
2 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 77330

Name of Operator: SG INTERESTS I LTD

Address: 100 WAUGH DR SUITE 400

City: HOUSTON State: TX Zip: 77007

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Amanda Blanchard

970-385-0696

ablanchard@sginterests.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 688800522

Inspection Date: 05/16/2019

FIR Submit Date: 05/20/2019

FIR Status: _____

Inspected Operator Information:

Company Name: SG INTERESTS I LTD

Company Number: 77330

Address: 100 WAUGH DR SUITE 400

City: HOUSTON State: TX Zip: 77007

LOCATION - Location ID: 423375

Location Name: MCINTYRE FLOWBACK PITS Number: 3 & 4 County: _____

Qtrqr: NWNE Sec: 26 Twp: 11S Range: 90W Meridian: 6

Latitude: 39.076344 Longitude: -107.413630

FACILITY - API Number: 05-051- -00 Facility ID: 421066

Facility Name: McIntyre Flowback Pits #3 and #4 Number: 421066

Qtrqr: NWNE Sec: 26 Twp: 11S Range: 90W Meridian: 6

Latitude: 39.076344 Longitude: -107.413630

CORRECTIVE ACTIONS:

1 CA# 125319

Corrective Action: Comply with Rule 603.f. Corrective action date taken from previous inspection.

Date: 01/14/2019

Response: FACTUAL REVIEW REQUEST

Basis for Review: Corrective action dates are not attainable

Operator Comment: The corrective action to remove the poly stored on site is unattainable as this equipment is necessary for ongoing operations. There are only three ways SG can transport produced water and poly is one of those ways. This equipment is necessary for ongoing operations until the flowback pits are permanently closed.

COGCC Decision: _____

COGCC
Representative:

2 CA# 125320

Corrective Action: Net or fence pit to prevent access per Rule 902.d.

Date: 05/21/2019

Response: CA COMPLETED

Date of Completion: 05/21/2019

Operator
Comment: Hole in net has been repaired. See attached photo.

COGCC Decision:

COGCC
Representative:

3 CA# 125321

Corrective Action: Lower fluid level so at least two feet of freeboard exists per Rule 902.b.

Date: 05/21/2019

Response: FACTUAL REVIEW REQUEST

Basis for Review: Corrective action dates are not attainable

Operator
Comment: SG has been working diligently since 4/10/2019 to reduce fluids as quickly as possible. The week of 4/10/19 had a big snow-melt event and in a matter of 2 days the extra freeboard did as it was intended to do and captured that snow-melt. There was no risk of overflow. In addition, the month of May has been a higher than average precipitation month so the efforts to reduce freeboard has taken longer. More trucks have been added to haul water out of the pits. Another suction and discharge line has been added at the injection well to load and unload faster. Again, SG will continue to work diligently to get back to the 2' freeboard, however the 5/21 due date is not attainable based on the weather.

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Please see attached CA responses.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Amanda Blanchard

Signed:

Title: Env & Reg Manager

Date: 5/23/2019 10:16:52 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402053185	Net repair photo
-----------	------------------

Total Attach: 1 Files