

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402030954

Date Received:

05/13/2019

FIR RESOLUTION FORM

CA Summary:

5 of 5 CAs from the FIR responded to on this Form

5 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10661

Name of Operator: BISON OIL & GAS II LLC

Address: 518 17TH STREET #1800

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Abigail Wenk

7206446997

awenk@bisonog.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 682504582

Inspection Date: 03/08/2019

FIR Submit Date: 03/12/2019

FIR Status: _____

Inspected Operator Information:

Company Name: BISON OIL & GAS II LLC

Company Number: 10661

Address: 518 17TH STREET #1800

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 452871

Location Name: Castor 8-59 Number: 19 County: _____

Qtrqr: NESE Sec: 19 Twp: 8N Range: 59W Meridian: 6

Latitude: 40.644946 Longitude: -104.011983

FACILITY - API Number: 05-123-00 Facility ID: 452871

Facility Name: Castor 8-59 Number: 19

Qtrqr: NESE Sec: 19 Twp: 8N Range: 59W Meridian: 6

Latitude: 40.644946 Longitude: -104.011983

CORRECTIVE ACTIONS:

1 ☒ CA# 123159

Corrective Action: Properly store materials in accordance with good housekeeping and proper materials management.

Date: 03/26/2019

Response: CA COMPLETED

Date of Completion: 03/14/2019

Operator
Comment:

Tanks were stored in accordance with good housekeeping and proper materials management and/or removed from location.

COGCC Decision: Approved pending re-inspection

Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an

COGCC Representative: acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

2 ☒ CA# 123160

Corrective Action: A disturbance area of 14.5 acres was mapped on 03/08/2019 via Trimble Juno 3B unit; this EXCEEDS the approved Form 2A for the permitted disturbance area of 12.2 acres.

Date: _____

Response: CA COMPLETED

Date of Completion: 05/02/2019

Operator Comment: An As Built survey was conducted showing the disturbance area of the pad to be under the permitted 12.2 acres. A copy of the as built survey was submitted with survey # 402013044.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Inspector will re-measure location upon follow-up inspection to verify total disturbance area of the location.

3 ☒ CA# 123161

Corrective Action: Conduct weed management and comply with Rule 1002.c.

Date: 04/12/2019

Response: CA COMPLETED

Date of Completion: 04/17/2019

Operator Comment: Work delayed due to weather and muddy pad conditions. Extension request submitted to COGCC in follow up survey but was denied. Weed management was conducted and will continue to be ongoing.

COGCC Decision: Approved pending re-inspection

COGCC Representative: COGCC Decision "Not Approved".
Operator response of "Corrective Action Complete" is a notification to the State that the corrective action has been addressed in its entirety. Based on operator comments corrective action does not appear to have been completed.

4 ☒ CA# 123162

Corrective Action: Comply with 603.f "good housekeeping" and 1003a. Remove and properly store or dispose of trash and debris from location.

Date: 04/12/2019

Response: CA COMPLETED

Date of Completion: 03/21/2019

Operator Comment: Trash and debris was removed from the location.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

5 ☒ CA# 123163

Corrective Action: If the Operator believes sufficient BMPs have been installed, then provide calculations from the site specific stormwater plan demonstrating that the installed BMPs are sufficient to prevent sediment laden storm runoff from leaving the location.

Date: 03/26/2019

If the operator determines that the current BMPs are insufficient, provide a site specific stormwater plan with specifications for controls that will be installed in order to bring location into compliance with Rule 1002.f(2).

Operator will be required to submit the stormwater plan via a Form 4 by 3/26/2019.

The installation and/or repair of stormwater and erosion control BMPs in accordance with good engineering practices are required by 4/12/2019

Response: CA COMPLETED

Date of Completion: 04/19/2019

Work delayed due to weather and muddy pad conditions. Extension request submitted to COGCC in follow up

Operator: sundry but was denied.
Comment: Stormwater and sediment control BMPs were repaired/installed. Maintenance of these BMPs is ongoing.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ariana Solis

Signed: _____

Title: Regulatory Analyst

Date: 5/13/2019 3:39:46 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402030954	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files