

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/29/2019

Submitted Date:

05/30/2019

Document Number:

697300085**FIELD INSPECTION FORM**

Loc ID 318333 Inspector Name: Graber, Candice (Nikki) On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
MacLaren, Joe		joe.maclaren@state.co.us	
Inspections, All		NBL_DJBU_Inspections@NB LENERGY.COM	
Aamold, Howard		Howard.Aamold@nblenergy.c om	
Evans, Jacob		jacob.evans@nblenergy.com	

General Comment:

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.

Photos attached to document site condition at the time of inspection.

Environmental**Waste Management:**

Type	Management	Condition	GPS (Lat)	(Long)
Oily Soil	Other	Adequate		
Comment	Stockpile present on location within footprint of pad.			
Corrective Action				Date: _____

Spill/Remediation:

Comment: There were no environmental personnel or contractors on site at the time of inspection. Rainwater from recent storm events was present in the bottom of the open excavation. Site characterization and remediation is ongoing. Excavation has extended south of initial spill discovery location. Subsidence observed adjacent to excavation. Operator shall ensure proper backfill and compaction procedures are followed. Work is proceeding under remediation #12591. The Form 19 Spill Report will remain open until corrective actions have been provided. Operator is granted 90 day extension to the initial due date; report is now due July 29, 2019.

Corrective Action: _____ Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697300086	Excavation With Rainwater	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4835464
697300087	Subsidence Observed Adjacent to Excavation	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4835465