

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402054282
Date Received:
05/30/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 74165
Name of Operator: RENEGADE OIL & GAS COMPANY LLC
Address: 6155 S MAIN STREET #210
City: AURORA State: CO Zip: 80016

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Espinosa	303-829-4982	billespinosa30@yahoo.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 685100915
Inspection Date: 05/07/2019 FIR Submit Date: 05/07/2019 FIR Status:

Inspected Operator Information:

Company Name: RENEGADE OIL & GAS COMPANY LLC Company Number: 74165
Address: 6155 S MAIN STREET #210
City: AURORA State: CO Zip: 80016

LOCATION - Location ID: 319728

Location Name: UPRR-HABEL-62S62W Number: 35NWNW County: ADAMS
Qtrqr: NWN Sec: 35 Twp: 2S Range: 62W Meridian: 6
W
Latitude: 39.838530 Longitude: -104.298560

FACILITY - API Number: 05-001-00 Facility ID: 201151

Facility Name: UPRR-HABEL Number: 1-35
Qtrqr: NWN Sec: 35 Twp: 2S Range: 62W Meridian: 6
W
Latitude: 39.838530 Longitude: -104.298560

CORRECTIVE ACTIIONS:

1 CA# 124954

Corrective Action: Properly treat or dispose of oily waste in accordance with 907.e Date: 09/15/2017

Response: CA COMPLETED Date of Completion: 05/17/2019

Operator Comment: Per 907.e - oil staining addressed

COGCC Decision:

COGCC
Representative:

2 CA# 124955

Corrective Action: Location is within a designated setback location, bullplug or cap all loadlines per Rule 604.c.(2)O.

Date: 09/15/2017

Response: CA COMPLETED

Date of Completion: 05/17/2019

Operator Comment: Renegade disagrees with this corrective action as location is NOT within a designated setback location per rule. Previous inspector for the area incorrectly categorized every facility as being a designated setback location without applying the required definition. A phone conversation held with Mike Leonard of the COGCC on 5/23/2019 confirmed that a corrective action was not appropriate. Renegade installed a loadline cap anyways.

COGCC Decision:

COGCC
Representative:

3 CA# 124956

Corrective Action: Comply with Rule 603.f .

Date: 09/15/2017

Response: CA COMPLETED

Date of Completion: 05/17/2019

Operator Comment: Renegade disagrees with the need for a corrective action issuance under Rule 603.f. A small amount of neatly stacked tubing and rods within the fenced off area around a pumping unit is NOT deemed unused equipment under Rule 603.f if used for the production of the well. This was confirmed via a phone conversation with Mike Leonard of the COGCC on 5/23/2019.

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Renegade disputes two of the three corrective actions sited in the field inspection from 5/7/2019. The remaining correction action has been addressed. Per conversation with Mike Leonard of the COGCC confirmed the historical interpretation of the rules sited in the corrective action differently from the interpretation of the field inspector.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edward Ingve

Signed:

Title: Manager/Owner

Date: 5/30/2019 1:36:35 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files