

Fee 5
API: 05-103-05745
Inspection: 679704295



Photo 1. Location looking southeast.

Fee 5
API: 05-103-05745
Inspection: 679704295



Photo 1. Half of well head sign missing.