

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/05/2019

Submitted Date:

06/05/2019

Document Number:

696101000**FIELD INSPECTION FORM**
 Loc ID 444377 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10071Name of Operator: HIGHPOINT OPERATING CORPORATIONAddress: 555 17TH ST STE 3700City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Watt, Dustin		dwatt@hpres.com	Sr. EHS Specialist
Allison, Rick		rick.allison@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
458793	WELL	DG	05/01/2019		123-48512	Fox Creek 12-63-33-0758B	DG

General Comment:

This is a DRILLING inspection.
Well: Drilling (DG).

Inspected FacilitiesFacility ID: 458793 Type: WELL API Number: 123-48512 Status: DG Insp. Status: DG**Well Drilling**

Rig: Rig Name: Savanna Drilling Rig Pusher/Rig Manager: Highpoint Operating
 Permit Posted: Yes Access Sign: Yes

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____
 Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: _____

Drill Fluids**Management:**

Lined Pit: _____ Unlined Pit: _____ Closed Loop: _____ Semi-Closed Loop: _____
 Multi-Well: _____ Disposal Location: _____

Comment: Drilling Contractor: Savanna Drilling. Rig #802.
 Site Supervisor: Highpoint Operating Corp.
 Observed posted Form 2 Doc #401747126.
 Observed prior BOP test charts provided by Highpoint Operating site supervisor.
 Observed Legals & name of Drill cuttings waste disposal provided by Highpoint Operating site supervisor.
 (SEC: 22, T: 6N, R: 61W, 1/4 1/4: W 1/2 NW 1/4. Krier's Land Farm).
 Observed open emergency flare: Not in operation at time of insp.

Observed Chemical Storage Area:
 1: Corrective Actions observed.
 Improper storage of Non E&P materials. Refer to Rule 907 A.
 Observed torn plastic coverings, Protective tarps on storage conex NOT shut.
 Approximately 1 gallon of spilled dry sodium bicarbonate powder on soil near storage conex.
 Highpoint Operating site supervisor was advised and stated that remediation for Corrective Actions would commence today.

Corrective Action: Remediate torn plastic coverings in storage conex. Shut protective tarps on storage conex.
 Remove & remediate spilled dry sodium bicarbonate powder on soil near storage conex.
 See photo #2.

Date: 06/07/2019

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On WED JUN 05, 2019 at approximately 13:57 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: HIGHPOINT OPERATING CORPORATION Location Name: Fox Creek /28 SWSE Location ID: 444377 Location County: Weld County, Colorado Weather: Partly cloudy / Damp from prior rain.</p> <p>While there, I observed: Well(s) - 1: Drilling (DG). Routine inspection. 1: Corrective Actions observed. 1.) Improper storage of Non E&P materials. Refer to Rule 907 A. Observed torn plastic coverings, Protective tarps on storage conex NOT shut. Approximately 1 gallon of spilled dry sodium bicarbonate powder on soil near storage conex. Highpoint Operating site supervisor was advised and stated that remediation for Corrective Actions would commence today. Remediate torn plastic coverings in storage conex. Shut protective tarps on storage conex. Remove & remediate spilled dry sodium bicarbonate powder on soil near storage conex. See photo #2. Corrective Action date: 06/07/2019.</p> <p>This is a summary of the inspection report.</p>	evinsb	06/05/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402066019	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4841547
696101001	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4841546