

Laramie Energy LLC
API # 05-077-09777
Inspection # 696600122



Photo #1 Photo from entrance of location.

Laramie Energy LLC
API # 05-077-09777
Inspection # 696600122



Photo #2 Photo from entrance of location

Laramie Energy LLC
API # 05-077-09777
Inspection # 696600122



Photo #3 Well heads and signs on location.



Photo #4 Photo taken of tank battery

Laramie Energy LLC
API # 05-077-09777
Inspection # 696600122



Photo#5 SW Slope need more stabilization. To prevent Erosion and Rilling BMP needs maintenance.



Photo#6 SW Slope need more stabilization. To prevent Erosion and Rilling BMP needs maintenance.

Laramie Energy LLC
API # 05-077-09777
Inspection # 696600122



Photo #7 BMP needs Maintenance on SW slope.

Photo #8 BMP needs Maintenance. Sediment moving over top of waddels

Laramie Energy LLC
API # 05-077-09777
Inspection # 696600122



Photo #9 BMP needs Maintenance. Silt Fence down on SW slope.



Photo #10 BMP needs Maintenance. Heave erosion and sediment moving.