

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402016273
Date Received:
04/22/2019

FIR RESOLUTION FORM

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672
Name of Operator: TIMBER CREEK OPERATING LLC
Address: 6295 GREENWOOD PLAZA BLVD #100
City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Santistevan, Vince	719-845-2102/719-680-9705	vincasantistevan@tcenergy.us
Mack, Ronald		ronaldmack@tcenergy.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 688401785
Inspection Date: 04/09/2019 FIR Submit Date: 04/09/2019 FIR Status:

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC Company Number: 10672
Address: 1001 17TH STREET #1000
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 309291

Location Name: GOLDEN EAGLE-633S67W Number: 30SENW County: LAS ANIMAS
Qtrqtr: NENW Sec: 30 Twp: 33S Range: 67W Meridian: 6
Latitude: 37.146672 Longitude: -104.928421

FACILITY - API Number: 05-071-00 Facility ID: 291279

Facility Name: GOLDEN EAGLE Number: 30-3
Qtrqtr: NENW Sec: 30 Twp: 33S Range: 67W Meridian: 6
Latitude: 37.146672 Longitude: -104.928421

CORRECTIVE ACTIONS:

1 CA# 124038

Corrective Action: Install proper guy line markers per Rule 1003.a Date: 04/30/2019

Response: CA COMPLETED Date of Completion: 04/12/2019

Operator Comment: A red post was installed to mark the Deadman anchor. See attached photo log for details.

COGCC Decision: Approved via an AMI

COGCC Representative: Based on Photos subitted be operator all corrective action have been completed. See inspection Doc# 693500446.

2 CA# 124039

Corrective Action: Comply with Rule 603.f .
For unused , unmarked flowline risers 24 hrs to lock out tag out.
30 days to remove riser.

Date: 04/10/2019

Response: CA COMPLETED Date of Completion: 04/10/2019

Operator Comment: All risers were marked and LOTO.

COGCC Decision: Approved via an AMI

COGCC Representative: Based on Photos subitted be operator all corrective action have been completed. See inspection Doc# 696500446.

3 CA# 124040

Corrective Action: Location is within a designated setback location, install fencing per Rule 604.c.(2)M.

Date: 05/09/2019

Response: CA COMPLETED Date of Completion: 04/12/2019

Operator Comment: The fence surrounding the production pit was repaired.

COGCC Decision: Approved via an AMI

COGCC Representative: Based on Photos subitted be operator all corrective action have been completed. See inspection Doc# 693500446.

4 CA# 124041

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 05/09/2019

Response: CA COMPLETED Date of Completion: 04/19/2019

Operator Comment: The erosion of the fill slope along the main access road was corrected. Rip-rap was placed in these areas for erosion control and to stabilize the soil.

COGCC Decision: Approved via an AMI

COGCC Representative: Based on Photos subitted be operator all corrective action have been completed. See inspection Doc# 693500446.

OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions have been addressed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed: _____

Title: SR. Environmental Tech.

Date: 4/22/2019 12:07:59 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402016273	FIR RESOLUTION SUBMITTED
402016328	Photo Log

Total Attach: 2 Files