

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402078222
Date Received:
06/18/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 1199 MAIN AVENUE SUITE 101
City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
-		SanJuanCOGCC@bp.com
Beebe, Sabre		sabre.beebe@bpx.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693900337
Inspection Date: 05/17/2019 FIR Submit Date: 05/22/2019 FIR Status:

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000
Address: 1199 MAIN AVENUE SUITE 101
City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 306851

Location Name: KENNEDY GU A-M34N8W Number: 21NWNW County: LA PLATA
Qtrqr: NWN Sec: 21 Twp: 34N Range: 8W Meridian: M
W
Latitude: 37.180803 Longitude: -107.727693

FACILITY - API Number: 05-067-00 Facility ID: 269664

Facility Name: KENNEDY A Number: 2
Qtrqr: NWN Sec: 21 Twp: 34N Range: 8W Meridian: M
W
Latitude: 37.180803 Longitude: -107.727693

CORRECTIVE ACTIIONS:

1 CA# 125424

Corrective Action: Control weeds. Due to the extent of the infestation here and surrounding oil and gas locations multiple control methods and applications will be needed.
Revegetation and stabilization measures need to be installed in portions of the interim reclamation area that are poorly revegetating, such as the eastern fill slope and the cut-slopes (northern and western). Revegetation and stabilization activities need to be completed no later than June 30, 2019.

Date: 06/09/2019

Response: CA COMPLETED

Date of Completion: 06/07/2019

Operator Comment: Noxious weeds treated within the lease area with herbicide. see attached

COGCC Decision:

COGCC Representative:

2 CA# 125425

Corrective Action: Stormwater controls along the access road need maintenance. Stabilization measures for erosion controls are needed along the well pad cut-slopes until long term stabilization is achieved.

Date: 06/30/2019

Response: CA COMPLETED

Date of Completion: 06/07/2019

Operator Comment: Seeding and hydromulching performed along cut areas of the lease in an attempt to re-establish vegetation via vegetation see attached.

COGCC Decision:

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions completed see attached

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe Signed:

Title: Compliance Specialist Date: 6/18/2019 7:15:36 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (http://ogccweblink.state.co.us/) - Search by Document Number.

Table with 2 columns: Document Number, Description. Row 1: 402078225, completion photos

Total Attach: 1 Files