

Operator's Area Review Contact:											
AREA OF REVIEW OFFSET WELL EVALUATIONS											
Offset Well API #	Offset Well Name	Offset Well Operator	Offset Well Status	Depth of Base of Aquifer	Offset Well Surface Casing Setting Depth	Offset Well Completed Formation Top	Offset Well Top of Production Casing Cement	Abandoned Wells	Active Wells		Comment
								To be Replugged	Requires Casing Repair	To be Plugged	
05-123-07218	UPRR 34 PAN AM 1	AMOCO PRODUCTION COMPANY	DA	545	221	7410		No	No	No	This well does not penetrate the proposed injection zone
05-123-10345	PHILLIP 1	ENERGY MINERALS CORP	AB	545	584	6817	0	No	No	No	This well does not penetrate the proposed injection zone
05-123-11119	CHAMPLIN 1-17	MONAHAN* REX FAMILY TRUST	DA	680	264	7298		No	No	No	This well does not penetrate the proposed injection zone
05-123-44047	EWS 4A	EWS 4 DJ BASIN LLC	IJ	545	1000	8443	940	No	No	No	
05-123-07611	ELMER KAUFMAN 2	FOUNDATION ENERGY MANAGEMENT LLC	PR	796	140	7306	0	No	No	No	This well does not penetrate the proposed injection zone
05-123-07865	ELMER KAUFMAN 3	U S MINERALS EXPL	AB	700	200	7344	0	No	No	No	This well does not penetrate the proposed injection zone
05-123-07952	KAUFMAN 4	FOUNDATION ENERGY MANAGEMENT LLC	SI	730	110	7286	0	No	No	No	This well does not penetrate the proposed injection zone
05-123-40000	ELMER KAUFMAN 1	SANDS-AMERICAN CORP	AB	798	7432	7372	0	No	No	No	This well does not penetrate the proposed injection zone
05-123-44167	EWS 4	EWS 4 DJ BASIN LLC	IJ	660	1000	8505	920	No	No	No	
05-123-14249	BERGLUND MYERS 42-19	SIMMONS ENERGY CORP	DA	660	172	7346	0	No	No	No	This well does not penetrate the proposed injection zone
05-123-08906	WRIGHT 1	SUMMIT OIL CO	DA	425	216	7299		No	No	No	This well does not penetrate the proposed injection zone