

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402079647

Date Received:

06/18/2019

## FIR RESOLUTION FORM

### CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1775 SHERMAN STREET - STE 3000

City: DENVER State: CO Zip: 80203

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Zack Liesenfeld

9705069276

zack.liesenfeld@pdce.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 697500207

Inspection Date: 06/10/2019

FIR Submit Date: 06/14/2019

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: PDC ENERGY INC

Company Number: 69175

Address: 1775 SHERMAN STREET - STE 3000

City: DENVER State: CO Zip: 80203

### LOCATION - Location ID: 319511

Location Name: Zeiler Number: SW-7 Pad County: \_\_\_\_\_

Qtrqr: SWS Sec: 7 Twp: 5N Range: 67W Meridian: 6  
W

Latitude: 40.409990 Longitude: -104.941200

### FACILITY - API Number: 05-123-00 Facility ID: 319511

Facility Name: Zeiler Number: SW-7 Pad

Qtrqr: SWS Sec: 7 Twp: 5N Range: 67W Meridian: 6  
W

Latitude: 40.409990 Longitude: -104.941200

### CORRECTIVE ACTIONS:

1 CA# 126158

Corrective Action: Install or repair required BMPs per Rule 1002.f. in accordance with good engineering practices. Corrective action date is the date the location was observed out of compliance, as the location should be in compliance at all times.

Date: 06/10/2019

Response: CA COMPLETED

Date of Completion: 06/10/2019

Operator  
Comment:

Stormwater BMPs were repaired in accordance with good engineering practices.

COGCC Decision: **Not Approved**

COGCC Representative: Operator indicates the corrective action was performed on June 10, 2019; however, the Field Inspection Report was not submitted until June 14, 2019. Operator did not provide a time stamp on their photos that would indicate the corrective action was completed on June 10, 2019.

Also, it doesn't appear the Operator has implemented long-term stormwater BMPs to prevent sediment laden stormwater from leaving location. Appears the Operator has only made repairs by regrading and tracking with equipment which are only temporarily BMPs.

**OPERATOR COMMENT AND SUBMITTAL**

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Zachary Liesenfeld

Signed:

Title: EHS Rep

Date: 6/18/2019 3:30:54 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
402079647	FIR RESOLUTION SUBMITTED
402079679	Zeiler Looking South
402079681	Zeiler Looking East

Total Attach: 3 Files