

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402080821

Date Received:

06/20/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10459
Name of Operator: EXTRACTION OIL & GAS INC

Address: 370 17TH STREET SUITE 5300

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Jeff Rickard

rickard.jeff@gmail.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 697500195

Inspection Date: 06/04/2019

FIR Submit Date: 06/13/2019

FIR Status: _____

Inspected Operator Information:

Company Name: EXTRACTION OIL & GAS INC

Company Number: 10459

Address: 370 17TH STREET SUITE 5300

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 455317

Location Name: Livingston Pad Number: _____ County: _____

Qtrqr: NWSE Sec: 7 Twp: 1S Range: 68W Meridian: 6

Latitude: 39.978564 Longitude: -105.040122

FACILITY - API Number: 05-014- -00 Facility ID: 455317

Facility Name: Livingston Pad Number: _____

Qtrqr: NWSE Sec: 7 Twp: 1S Range: 68W Meridian: 6

Latitude: 39.978564 Longitude: -105.040122

CORRECTIVE ACTIONS:

1 CA# 126115

Corrective Action: Please provide documentation that illustrates what portions of fill and cut slopes have been incorporated with topsoil, the depth of topsoil along the portions of fill and cut slopes where it has been incorporated, and how the Operator will identify that topsoil to facilitate subsequent reclamation.

Date: 06/20/2019

Response: CA COMPLETED

Date of Completion: 06/19/2019

Operator Comment: Attached is a Figure that shows where the topsoil has been incorporated into the slopes of the location. The topsoil is spread out to an average depth of 8" (approx. same depth as identified before construction) and will be seeded and maintained through the life of the location until final reclamation. Signs have been placed in the areas where topsoil was spread that identify the topsoil and will remain there until final reclamation.

COGCC Decision: _____

COGCC
Representative: _____

2 CA# 126116

Corrective Action: Install or repair required BMPs per Rule 1002.f. in accordance with good engineering practices. Corrective action date is the date the location was observed out of compliance, as it should be in compliance at all times.

Date: 06/04/2019

Response: CA COMPLETED

Date of Completion: 06/07/2019

Operator
Comment: The slopes were stabilized on 6/7/19 when the equipment operator felt the slope had dried out enough to safely operate the equipment.

COGCC Decision: _____

COGCC
Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jeff Rickard

Signed: _____

Title: Regulatory Compliance Coo

Date: 6/20/2019 8:36:09 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402080865	Topsoil Layout
-----------	----------------

Total Attach: 1 Files