

South Sulphur 1
API: 05-103-05041
Inspection: 679704625



Photo 1. Location.

South Sulphur 1
API: 05-103-05041
Inspection: 679704625



Photo 2. Top of P&A marker with several pin holes in welds venting gas.

South Sulphur 1
API: 05-103-05041
Inspection: 679704625



Photo 3. Gas filled bag on well head.