

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/01/2019

Submitted Date:

07/02/2019

Document Number:

689900953**FIELD INSPECTION FORM**Loc ID 307280 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10672Name of Operator: TIMBER CREEK OPERATING LLCAddress: 6295 GREENWOOD PLAZA BLVD #100City: GREENWOOD State: CO Zip: 8111-**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		ediefitzgerald@tcenergy.us	
		robfoos@tcenergyllc.com	
Mack, Ronald		ronaldmack@tcenergy.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
217354	WELL	PR	01/01/1995	GW	071-06130	APACHE CANYON 14-1	RI

General Comment:

This is a follow up of the previous inspection #689900634.

Not all corrective actions of previous inspection have been performed.

Location**Lease Road:**

Type	Main		
comment:	Road damage. See stormwater section.		
Corrective Action	L	Date:	

Overall Good: ☐**Emergency Contact Number:**

Comment:		Date:	
Corrective Action:			

Good Housekeeping:

Type	OTHER		
Comment:	The oily waste on engine skid was cleaned up.		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment:		Culverts along the road were cleaned out. There is vehicle rutting and road damage along the main road leading to the location. These areas need to be graded and may need gravel and compaction. Stormwater needs to be diverted off the road. Previous corrective action date remains for possible enforcement. Corrective action needs to be performed immediately. See Attached Photos				
Corrective Action:		Install or repair required BMPs per Rule 1002.f.				Date: 05/15/2019
Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689900954	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4867588