

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/25/2019

Submitted Date:

07/05/2019

Document Number:

688800578**FIELD INSPECTION FORM**
 Loc ID 335966 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10091Name of Operator: BERRY PETROLEUM COMPANY LLCAddress: 5201 TRUXTUN AVENUE #100City: BAKERSFIELD State: CA Zip: 90339**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Wilbourn, Don		dwilbourn@bry.com	
Heil, John		john.heil@state.co.us	
Johnson, Derek	970-285-2200	djohnson@bry.com	Dist. Superintendent

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
443338	LAND APPLICATION SITE	AC	09/25/2015		-	Chevron O06 696 443338	EI

General Comment:

On June 25, 2019 COGCC Environmental Supervisor Alex Fischer, and EPS staff members John Heil and Jim Hughes conducted an environmental field inspection of the Berry Petroleum Company LLC Chevron O06 Land Application Site #443338. For the most recent environmental field inspection report of this facility, please refer to document #688800357. Berry Petroleum representatives Derek Johnson and Don Wilbourn, and Dave Nicholson from Nicholson GeoSolutions LLC were on site during this inspection.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	OTHER		
Comment:	Free standing sign near location entrance.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Posted on location sign.		
Corrective Action:		Date:	

Good Housekeeping:			
Type	DEBRIS		
Comment:	Continue to remove liner pieces as they become exposed in land farmed material.		
Corrective Action:		Date:	

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Environmental**Waste Management:**

Type	Management	Condition	GPS (Lat) (Long)	
Drill Cuttings	Land Treatment	Adequate		
Comment	Please refer to REM #10050 for more information regarding the land farm project on this location.			
Corrective Action				Date:

Spill/Remediation:

Comment:			
Corrective Action:			Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Self Inspection	Pass	
				Material Handling And Spill Prevention	Pass	

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On June 25, 2019 COGCC West Environmental Supervisor Alex Fischer, and EPS staff members John Heil and Jim Hughes conducted an environmental field inspection of the Berry Petroleum Company LLC Chevron O06 Land Application Site #443338. For the most recent environmental field inspection report of this facility, please refer to document #688800357. Berry Petroleum representatives Derek Johnson and Don Wilbourn, and Dave Nicholson from Nicholson GeoSolutions LLC were on site during this inspection. The treatment cells on this location were recently turned by a tractor. Continue to remove liner pieces from land farm as they become exposed.	hughesjo	07/05/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800579	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4869526