

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/08/2019

Submitted Date:

07/08/2019

Document Number:

693500579**FIELD INSPECTION FORM**

Loc ID 335697 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Adamczyk, Megan		megan.adamczyk@state.co.us	
Lara-Mesa, Susana	303-825-4822	cogcc@kpk.com	All inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275817	WELL	SI	12/01/2018	GW	001-09531	STANDLEY 8-3	SI

General Comment:

Inspected Facilities

Facility ID: 275817 Type: WELL API Number: 001-09531 Status: SI Insp. Status: SI

Complaint

Comment: Inspection in response to complaint.
 Field Inspector Assigned: Randy Silver
 Complaint Received
 Date: 07-03-2019
 Complaint Contacted:
 Date: 07-04-2019 Time: 7-04-19 9:27AM left voice mail.
 Location ID # 335697
 Inspection Document # 693500574
 Complaint Document #200447502
 Nature of Complaint: flaring
 Field Inspector Actions:
 On 07-03-2019, I Randy Silver area field inspector was assigned a complaint received by COGCC staff in reference to flaring.
 On 07-04-2019, I attempted to make contact with the complainant Rob Migliore 15765 Josephine Cir E Thornton CO; complainant indicated that on 7-03-19 saw flaring Adjacent to Costco in north Thornton CO.
 I performed a complete site inspection of the oil and gas location and associated wells in the area. At time of inspection.
 At time of inspection, I spoke with Phip Reyna KPK rig supervisor; he stated they were setting bridge plugs on wells for Interchange frac. Rig crew flared for approx... Two hrs. when they opened the well.
 Weather conditions: Clear
 See inspection document #693500574 per my inspection.
 No violation of COGCC rules were observed at the time of the inspection.
 All information reviewed and site inspection information were submitted to the COGCC for further review.

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
See doc# 693500574 for full inspection.	silverr	07/08/2019