

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/01/2019

Submitted Date:

07/08/2019

Document Number:

697500287

FIELD INSPECTION FORM

Loc ID 319511 Inspector Name: Binschus, Chris On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 69175
Name of Operator: PDC ENERGY INC
Address: 1775 SHERMAN STREET - STE 3000
City: DENVER State: CO Zip: 80203

Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|--------------------------|---------------------------------|
| , | | cogccinspection@pdce.com | ALL INSPECTIONS |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|----------|--------|-------------|------------|---------|-----------------|-------------|
| 319511 | LOCATION | AC | | | - | Zeiler SW-7 Pad | RI |

General Comment:

[This is a follow-up Interim Reclamation and Stormwater inspection to Doc. #697500207.](#)

Inspected Facilities

Facility ID: 319511 Type: LOCATION API Number: - Status: AC Insp. Status: RI

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment: [Operator is in process of responding to the previous corrective action Field Inspection Report. Refer to the attached inspection photos. Corrective action remains open until resolved.](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f. in accordance with good engineering practices. Corrective action date is the date the location was observed out of compliance, as the location should be in compliance at all times.](#)

Date: 06/10/2019

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

| Comment | User | Date |
|---------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|------------|
| Note: COGCC staff, Chris Binschus, denied the Operator Field Inspection Report Resolution form Doc. # 402079647 submitted on 6/18/2019. | binschusc | 07/08/2019 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 402099433 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4871383 |
| 697500288 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4871369 |