

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/03/2019

Submitted Date:

07/09/2019

Document Number:

697500295

**FIELD INSPECTION FORM**

Loc ID 416448 Inspector Name: Binschus, Chris On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10071  
Name of Operator: HIGHPOINT OPERATING CORPORATION  
Address: 555 17TH ST STE 3700  
City: DENVER State: CO Zip: 80202

**Findings:**

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
BARBER, MATT		mbarber@hpres.com	
		ssinger@hpres.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
416448	LOCATION	AC			-	Fox Creek 1-35H	RI

**General Comment:**

[This is an Interim Reclamation and Stormwater inspection.](#)

**Inspected Facilities**

Facility ID: 416448 Type: LOCATION API Number: - Status: AC Insp. Status: RI

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

**Comment:** This location is not in compliance with Rule 1002.f. Operator has failed to implement long-term stormwater BMPs to prevent sediment laden stormwater from leaving location. Sediment discharge was observed off Location along the entire western perimeter. Refer to the attached inspection photos.

**Corrective Action:** Install or repair required BMPs per Rule 1002.f. in accordance with good engineering practices. Corrective action date is the date to location was observed out of compliance, as the location should be in compliance at all times.  
  
Operator shall take measures to comply with Rule 1004 throughout the impacted areas off Location.

**Date:** 07/03/2019

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402100258	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4872165">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4872165</a>
697500296	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4872163">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4872163</a>