

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/15/2019

Submitted Date:

07/15/2019

Document Number:

685101328

FIELD INSPECTION FORM

Loc ID 317973 Inspector Name: MEDINA, JUSTIN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 31257
Name of Operator: FRITZLER RESOURCES INC
Address: P O BOX 114
City: FORT MORGAN State: CO Zip: 80701

Findings:

- 10 Number of Comments
- 6 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Fritzler, Gene	(970) 867-9388	gfritzler@bresnan.net	
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240288	WELL	PR	07/07/1997	GW	123-08076	HOPKINS 41C-19 2	PR

General Comment:

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	no capacity label on water tank/illegible		
Corrective Action:	Install sign to comply with Rule 210.d.		Date: 06/22/2019
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____
Good Housekeeping:			
Type	OTHER		
Comment:	Mechanical issue: piping in separator appears to be leaking on ground.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date: 06/22/2019
Type	TRASH		
Comment:	blue bucket by pumpjack		
Corrective Action:	Comply with rule 603 f		Date: 06/05/2019
Type	OTHER		
Comment:	Stained soil inside separator house / outside of separator house		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e		Date: 06/22/2019
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Horizontal Heated Separator	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Electric box		
Corrective Action:			Date:
Type: Bird Protectors	# 1		

Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1		PBV STEEL		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	shares containment with oil tank			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	YES		
--------	-----	--	--

Comment:	Pilot appears not to be lit on heater on separator.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	05/23/2019

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 240288 Type: WELL API Number: 123-08076 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Fail	
Comment: Storage of chemicals and material						Date: <u>06/05/2019</u>
Corrective Action: Install adequate BMB for storage of materials that could result in the discharges causing pollution of surface waters per rule 1002 f (2) B						
Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments		
Comment	User	Date
<p>COGCC Inspection Report Summary On 7/15/19 at approximately 1200 I, Inspector Justin Medina conducted an on-site inspection at Fritzier Resouces Inc.- API 123-08076 -Hopkins 41C-19 2 Weld County Colorado.</p> <p>While there, I observed Producing Well During this inspection the following possible compliance issues were observed: Follow up inspection for Document # 693500136 Corrective Actions from previous inspection are delinquent. no capacity label on water tank/illegible Install sign to comply with Rule 210.d. 6/22/19 Mechanical issue: piping in separator appears to be leaking on ground. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. 6/22/19 Stained soil inside seperator house / outside of separator house Properly treat or dispose of oily waste in accordance with 907.e 6/22/19 blue bucket by pumpjack Comply with rule 603 f 6/5/19 Pilot appears not to be lit on heater on separator. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.5/23/19 Storage of chemicals and material Install adequate BMB for storage of materials that could result in the discharges causing pollution of surface waters per rule 1002 f (2) B 6/5/19 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	medinaj	07/15/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685101329	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4880296