

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/08/2019

Submitted Date:

07/16/2019

Document Number:

688305148**FIELD INSPECTION FORM**

Loc ID Inspector Name: On-Site Inspection ☐
 320752 Sherman, Susan 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10362Name of Operator: S & D LLCAddress: 7119 SILVER MOON LANECity: FORT COLLINS State: CO Zip: 80525**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Heffner, Taylor	303-219-3362	theffner@phxresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
204792	WELL	SI	01/01/2017	GW	005-06877	DANIEL KISSLER 1-9	PA

General Comment:

PA Inspection

Inspected FacilitiesFacility ID: 204792 Type: WELL API Number: 005-06877 Status: SI Insp. Status: PA**Cement**Cement ContractorContractor Name: SWABBCO

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging OperationsDepth Plugs(feet range): all plugsCement Volume (sx): 151

Good Return During Job: _____

Cement Type: Class G

Comment: 7/10/2019 Toby cut pipe @ 1830' can't pull it
 Cutter wireline
 7/11/2019
 Cut @ 1830'
 Perfs @ 1680'
 CICR @ 1635'
 SWABBCO pumped 30 sxs below retainer at 1000 psi
 7/12/2019
 Cutter ran CBL from 1642', sent to COGCC Denver Engineer (DB), it was decided to
 dump 2 sxs on top on retainer and pump cement from 1300' of tubing to surface, took
 115 sxs of 15.8 ppg, Class G cement to get cement returns at surface, will tag cement at
 cut, cap and cover of wellhead-operator to notify inspector of this activity prior to work

Corrective Action: _____

Date: _____

WorkoverComment: Toby's Oilfield Services Rig 1

Corrective Action: _____

Date: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688305260	S&D LLC, Daniel Kissler 1-9 PA 7_10_19	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4880420
688305261	S&D LLC, Daniel Kissler 1-9 PA 7_12_19	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4880421
688305262	S&D LLC, Daniel Kissler 1-9 PA 7_11_19	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4880422
688305263	S&D LLC, Daniel Kissler 1-9 PA 7_12_19	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4880423