

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/15/2019

Submitted Date:

07/15/2019

Document Number:

687905155**FIELD INSPECTION FORM**

Loc ID      Inspector Name:      On-Site Inspection ☐  
 325672      Stewart, Joseph      2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 96735Name of Operator: WILLIFORD RESOURCES, L.L.C.Address: 6506 S LEWIS AVE STE 102City: TULSA      State: OK      Zip: 74136**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**12 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Stevens, Glenn	(970) 749-0192	glennstevens@centurylink.net	
Callahan, Linda	(918) 712-8828	lcallahan3@swbell.net	e-mail receipient

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215209	WELL	PR	05/28/2003	OW	067-06814	PAYNE-SCHMITT 1	PR

**General Comment:**[Site inspection with photos at the end of this report.](#)

<b>Location</b>					
<b>Lease Road:</b>					
Type	Access				
comment:	Two-track dirt road on private property.				
Corrective Action					Date:
Overall Good: <input type="checkbox"/>					
<b>Signs/Marker:</b>					
Type	TANK LABELS/PLACARDS				
Comment:	Tank labels/placards are fading and starting to come off storage tanks.				
Corrective Action:					Date:
Type	WELLHEAD				
Comment:	Sign posted at wellhead.				
Corrective Action:					Date:
Emergency Contact Number:					
Comment:	Contact information and 911 posted on sign.				
Corrective Action:					Date: _____
<b>Good Housekeeping:</b>					
Type	WEEDS				
Comment:	Weeds around pump jack.				
Corrective Action:	Control weeds around equipment per Rule 603.f.				Date: 07/25/2019
Overall Good: <input type="checkbox"/>					
<b>Spills:</b>					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
<b>Equipment:</b>					
					corrective date
Type: Flow Line	# 2				
Comment:	1-2" flowline from wellhead to oil tanks. 1-1" flowline from wellhead to pumpjack engine fuel gas.				
Corrective Action:					Date:
Type: Ancillary equipment	# 1				
Comment:	Wellhead.				
Corrective Action:					Date:
Type: Prime Mover	# 1				
Comment:	Prime mover has engine oil leak staining soil below it.				
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.				Date: 08/15/2019
<b>Tanks and Berms:</b>					
Contents	#	Capacity	Type	Tank ID	SE GPS

CRUDE OIL	2	200 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:
<b>Paint</b>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:						Date:
<b>Venting:</b>						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
<b>Flaring:</b>						
Type						
Comment:						
Corrective Action:						Date:

<b>Inspected Facilities</b>				
Facility ID: 215209	Type: WELL	API Number: 067-06814	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing.			
Corrective Action:				Date:

--

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass	Culverts	Pass			
				Material Handling And Spill Prevention	Fail	
Compaction	Pass	Compaction	Pass			

Comment: Spill prevention for 55 gallon drums is inadequate because the drain plug in the bottom is missing. It will not hold liquid in the event of a spill.

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 08/15/2019

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402109540	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4879095">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4879095</a>
687905169	Spill prevention missing plug.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4879072">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4879072</a>
687905170	Weeds around equipment.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4879073">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4879073</a>
687905171	Engine oil leak.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4879074">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4879074</a>