

# Inspection Photos

07/23/2019

Operator: GRAND MESA OPERATING CO #  
35080

Location ID: 463974  
Lincoln County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

## Inspection Photos

Operator Name: GRAND MESA OPERATING CO # 35080

Location ID: 463974



**Photo 1:** Photos 1-4 taken from the south end of the location, facing west, northwest, northeast to east. Photos show overview of the location. Location subject to final reclamation in accordance with 1004.a. No final reclamation activities appear to have been conducted at time of inspection. Location and access road will require, at a minimum, pit closure, removal of cattle guard, compaction alleviation (cross ripping to a minimum of 18 inches), recontouring/regrading (returning soils) and revegetation activities on the access road and location will need to be conducted

**Photo 2:** See comments under photo 1.

## Inspection Photos

Operator Name: GRAND MESA OPERATING CO # 35080

Location ID: 463974



**Photo 3:** See comments under photo 1.



**Photo 4:** See comments under photo 1.

## Inspection Photos

Operator Name: GRAND MESA OPERATING CO # 35080

Location ID: 463974



**Photo 5:** Photo taken from the west end of the location, facing north. Photo shows ditch/berm stormwater BMP, surface roughening (ripping) and tracking stormwater controls.



**Photo 6:** Photo taken from the west end of the location, facing east. Photo shows tracking on slopes appear to be in proper functioning condition.

## Inspection Photos

Operator Name: GRAND MESA OPERATING CO # 35080

Location ID: 463974



**Photo 7:** Photo taken from the northwest corner of the location, facing north. Photo shows stormwater erosion has filled the ditch with sediment. BMP requires maintenance.



**Photo 8:** Photo taken from the northwest corner of the location, facing east. Photo shows erosion degradation evident between the pad and the topsoil stockpile on the northwest end of the location.

## Inspection Photos

Operator Name: GRAND MESA OPERATING CO # 35080

Location ID: 463974



**Photo 9:** Photo taken from the access road, facing south. Access road requires reclamation in accordance with 1004.a including, but not limited to, compaction alleviation (cross-ripping to a depth of 18 inches), recontouring/regrading and revegetating.



**Photo 10:** Photo taken from the access road. Photo shows cattle guard. Cattle guard will need to be removed and access road reclaimed in accordance with 1004.a