

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402125662

Date Received:

07/29/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10351

Name of Operator: WAPITI OPERATING LLC

Address: 1310 W SAM HOUSTON PKWY N

City: HOUSTON State: TX Zip: 77043

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
Randy Madison	575-445-6706	rmadison@wapitienergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 689901030

Inspection Date: 07/19/2019

FIR Submit Date: 07/19/2019

FIR Status: _____

Inspected Operator Information:

Company Name: ARP PRODUCTION COMPANY LLC

Company Number: 10471

Address: 425 HOUSTON STREET SUITE 300

City: FORTH WORTH State: TX Zip: 76102

LOCATION - Location ID: 308367

Location Name: VPC C-635S67W Number: 11NESE County: LAS ANIMAS

Qtrqr: NESE Sec: 11 Twp: 35S Range: 67W Meridian: 6

Latitude: 37.008650 Longitude: -104.851610

FACILITY - API Number: 05-071-00 Facility ID: 269528

Facility Name: VPC C Number: 121

Qtrqr: NESE Sec: 11 Twp: 35S Range: 67W Meridian: 6

Latitude: 37.008650 Longitude: -104.851610

CORRECTIVE ACTIONS:

1 CA# 128360

Corrective Action: Comply with Rule 1003.f.
Control noxious weeds.

Date: 07/11/2019

Response: CA COMPLETED

Date of Completion: 07/25/2019

Operator Comment: Weeds have been treated again in some locations. Weeds were also disced down on the side hill. See attached pictures.

COGCC Decision: _____

COGCC
Representative:

2 CA# 128361

Corrective Action: Comply with the 1003 interim reclamation rules.
Reseed and stabilize the cut slope.

Date: 07/20/2019

Response: CA COMPLETED

Date of Completion: 07/25/2019

Operator
Comment:

The slop has been reseeded. See attached photos of the drill marks and seed.

COGCC Decision:

COGCC
Representative:

3 CA# 128362

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 07/20/2019

Response: CA COMPLETED

Date of Completion: 07/25/2019

Operator
Comment:

2 new culverts have been installed on the lenght of the hill. The 2 damaged culverts have have been opened up so they will flow. Rock aprons have been installed on the down flow side. The erosion has been filled in with rock to prevent erosion in the barrow ditch alongside the road. See attached pictures.

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Randy L. Madison

Signed: _____

Title: HSE Specialist

Date: 7/29/2019 2:49:34 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number Description

402125694	Pictures C-121 CA's complete
-----------	------------------------------

Total Attach: 1 Files