

Bonanza Creek Energy Operating, Inc.
Daily Completion/Workover Report

<input type="checkbox"/> New Drill		<input type="checkbox"/> Recompletion		<input type="checkbox"/> LOE		<input type="checkbox"/> Re-Frac		<input type="checkbox"/> Casing Repair		<input checked="" type="checkbox"/> T/A	
Date: 10-Apr-19		Well Name: Antelope 11-20						AFE: CO11504		18184..91, 18200..01	
Legal Desc: NWNW		Sec: 20		Twn: 5N		Rng: 62W					
Perforations		Surface Csg: 11 jts		Size: <u>8 5/8"</u>		Wt/Gd: <u>24#</u>		Conn. <u>ST&C 8RD</u>		Depth: <u>468'</u>	
		Production Csg: 161 jts		Size: <u>4 1/2"</u>		Wt/Gd: <u>11.6#</u>		Conn. <u>LT&C 8RD</u>		Depth: <u>6668'</u>	
		Rods:		Size: _____		Wt/Gd: _____		Top: _____		Depth: _____	
		Tubing: 191 jts		Size: <u>2 3/8"</u>		Wt/Gd: <u>J-55</u>		Conn. <u>EUE</u>		Depth: <u>6186'</u>	
		Packer: _____		RBP: _____		CIBP <u>6219'</u>		Sd Plug _____		Last Cleaned <u>6650'</u>	
		TD <u>6706'</u>		PBTD <u>6668'</u>		TOC <u>2436'</u>				Out To	
		Fluid Lost <u>6395</u>		Recovered <u>2195</u>		Load Remaining <u>4200</u>					
		Other Information: _____									
Job Objective: _____		Offset frac T/A _____									

Operation Past 24 Hours

SICP-80, SITP-60, SISP-0, MIRU RWS #15. Hold safety meeting and discuss JSA. Control well to the rig tank then pump a 50/30 bbl kill down the csg and tbp to get well on a strong vacuum. Breakdown the wellhead then RU to TOO H w/ 201 jts and lay down 9 jts. RU to TBIH w/ 10K HM CIBP and work to set w/ 192 jts at +/- 6219'. Plug is set 73' above the top Niobrara perfs at 6292'. RU and roll the hole clean of gas and oil then pressure test to 1000 psi and held for 10 min w/ no leak off. RU to pump 2 sks cmt and displace w/ 24 bbls then lay down one jt. ND the Bop's and repack the wellhead. EOT is landed w/ 191 jts at +/- 6186'. Clean up location and RD to move to the Antelope 22-20. Turn well over to prod, end of report. Offset frac prep to be charged to the Antelope J-20 pad AFE 18184..91, 18200..01.

Proposed Operations: _____	Well T/A for offset frac _____
Contractor: <u>RWS / Zito / Downhole / SEC</u>	Supervisor: <u>Kurt Dodge</u>