

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/31/2019

Submitted Date:

07/31/2019

Document Number:

693500938**FIELD INSPECTION FORM**

Loc ID 455317 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10459Name of Operator: EXTRACTION OIL & GAS INCAddress: 370 17TH STREET SUITE 5300City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Carlisle, J	970-534-6006	COGCCInspections@extracti onog.com	ALL INSPECTIONS
Adamczyk, Megan		megan.adamczyk@state.co.u s	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
455313	WELL	DG	06/05/2019		014-20755	Livingston S19-25-5C	DG

General Comment:

Inspected Facilities

Facility ID: 455313 Type: WELL API Number: 014-20755 Status: DG Insp. Status: DG

Complaint

Comment: Inspection in response to complaint.
 Field Inspector Assigned: Randy Silver
 Complaint Received
 Date: 07-29-2019
 Complaint Contacted:
 Date: 07-31-2019 Time: 8:55AM via phone
 Location ID #455317
 Inspection Document # 693500922
 Complaint Document #200447802
 Nature of Complaint: Noise
 Field Inspector Actions:
 On 07-30-2019, I Randy Silver area field inspector was assigned a complaint received by COGCC staff in reference to Noise. The complainant Mackenzie Carignan 3186 Blue Mountain Dr Broomfield CO stated the issues were occurring outside of complainants home.
 On 07-31-2019, I attempted to make contact with the complainant who indicated that on 7-27-19 she stated she could hear the whirring stop and start of what sounds like half siren, half jet engine, starting and stopping repeatedly. I informed her at the time of the complaint the rig crew had TD and was pulling drill pipe out of the hole.
 I performed a complete site inspection of the oil and gas location and associated wells in the area. At time of inspection, I did not observe any unusual sounds.
 At time of inspection, I spoke with Danny Herra drilling supervisor he stated at time of complaint they had TD and were pulling pipe out of the hole. At time of inspection crew was performing normal drilling operations.
 Weather conditions: Clear, location was dry
 See inspection document #693500922 per my inspection.
 No violation of COGCC rules were observed at the time of the inspection.
 All information reviewed and site inspection information were submitted to the COGCC for further review.

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
See Doc#693500922 for full inspection	silverr	07/31/2019