

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402047255
Date Received:
05/20/2019

FIR RESOLUTION FORM

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10559
Name of Operator: SOUTHLAND ROYALTY COMPANY LLC
Address: 400 WEST 7TH STREET
City: FORT WORTH State: TX Zip: 76102
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Elgin, Jerry		jelgin@mspartners.com
Blaylock, Connie		cblaylock@mspartners.com
Gallenbeck, Danny		dgallenbeck@ctfieldsvc.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 689802617
Inspection Date: 05/02/2019 FIR Submit Date: 05/08/2019 FIR Status:

Inspected Operator Information:

Company Name: EOG Y RESOURCES INC Company Number: 97810
Address: 105 SOUTH 4TH ST
City: ARTESIA State: NM Zip: 88210

LOCATION - Location ID: 313308

Location Name: Landing Strip Unit-69N90W Number: 6NWSW County: MOFFAT
Qtrqr: NWS Sec: 6 Twp: 9N Range: 90W Meridian: 6
Latitude: 40.764000 Longitude: -107.539310

FACILITY - API Number: 05-081- -00 Facility ID: 285957

Facility Name: LANDING STRIP FEDERAL Number: 1
Qtrqr: NWS Sec: 6 Twp: 9N Range: 90W Meridian: 6
Latitude: 40.764000 Longitude: -107.539310

CORRECTIVE ACTIONS:

1 CA# 125014

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 05/17/2019

Response: CA COMPLETED

Date of Completion: 05/17/2019

Corrective Action has been completed - erosion repaired and new wattles installed.

Operator
Comment:

COGCC Decision: **Not Approved**

COGCC Representative: Wattles in photos 1-4 do not appear trenched. BMPs must be installed properly to be considered a BMP and not debris. Erosion on location may need combination of properly executed BMPs, one incorrectly installed BMP will not meet this corrective action.

OPERATOR COMMENT AND SUBMITTAL

Comment: Gully has been repaired and sediment in ditch removed.
Fill slope has been reseeded and erosion matting installed for additional stabilization.
Old wattles have been removed.
New wattles have been installed as of 5/17/2019.
See attached photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Connie Blaylock

Signed:

Title: Regulatory Analyst

Date: 5/20/2019 4:03:38 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402047255	FIR RESOLUTION SUBMITTED
402049599	PHOTO OF WORK 1
402049664	PHOTO OF WORK 2
402049666	PHOTO OF WORK 3
402049668	PHOTO OF WORK 4
402049670	PHOTO OF WORK 5

Total Attach: 6 Files