

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402089017
Date Received:
07/01/2019

FIR RESOLUTION FORM

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10559
Name of Operator: SOUTHLAND ROYALTY COMPANY LLC
Address: 400 WEST 7TH STREET
City: FORT WORTH State: TX Zip: 76102
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Blaylock, Connie		cblaylock@mspartners.com
Gallenbeck, Danny		dnr_cogccengineering@state.co.us
Elgin, Jerry		dgalenbeck@ctfieldsvcs.com
Allman, Stephanie	307-382-4005	jelgin@mspartners.com
		stephanie_allman@eogresources.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 689802842
Inspection Date: 06/11/2019 FIR Submit Date: 06/21/2019 FIR Status:

Inspected Operator Information:

Company Name: EOG Y RESOURCES INC Company Number: 97810
Address: 105 SOUTH 4TH ST
City: ARTESIA State: NM Zip: 88210

LOCATION - Location ID: 313060

Location Name: PEPPLER FEE-612N91W Number: 18SWNW County: MOFFAT
Qtrqtr: SWN Sec: 18 Twp: 12N Range: 91W Meridian: 6
Latitude: 40.997317 Longitude: -107.657625

FACILITY - API Number: 05-081- -00 Facility ID: 223491

Facility Name: PEPPLER FEE COM Number: 12-18
Qtrqtr: SWN Sec: 18 Twp: 12N Range: 91W Meridian: 6
Latitude: 40.997317 Longitude: -107.657625

CORRECTIVE ACTIONS:

1 ☒ CA# 126426

Corrective Action: Comply with Rule 603.f .

Date: 07/22/2019

Response: CA COMPLETED

Date of Completion: 06/27/2019

Operator Comment: Non-reportable spill: Stained soil was removed from the site and the hole filled-in with clean soil.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

2 ☒ CA# 126427

Corrective Action: Comply with Rule 603.f .

Date: 07/22/2019

Response: CA COMPLETED

Date of Completion: 06/27/2019

Operator Comment: Tubing and other debris have been removed from the location.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

3 ☒ CA# 126428

Corrective Action: Comply with Rule 603.f .

Date: 06/24/2019

Response: CA COMPLETED

Date of Completion: 06/26/2019

Operator Comment: A response by the due date of 6/24/19 was unattainable because the receipt of the FIR was a day after the due date, on 6/25/19.
On 6/26/2019, Southland Royalty Company LLC LO/TO the 3" steel risers at the location, photos attached. Upon inspection of the risers, it is suspected that the risers are the property of the pipeline company. A factual review is requested.
SRC is attempting to verify ownership.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Regarding flowline risers, 2 additional risers that were found in the fiberglass hut by the tank area have been LOTO (one 1" and one 2").

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Connie Blaylock

Signed: _____

Title: Regulatory Analyst

Date: 7/1/2019 3:58:51 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

402089017	FIR RESOLUTION SUBMITTED
-----------	--------------------------

402089083	Riser LOTO (2)
402089085	Riser LOTO (1)
402089086	Riser LOTO (3)
402093293	Stained Soil Removed
402093295	Stained Soil Removed
402093296	Stained Soil Removed
402093298	Debris Cleared

Total Attach: 8 Files