

Inspection Photos

API: 05-071-06223

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 8/8/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06223 | Date: 8/8/2019

Inspection Photos



Photo 1. The culvert near the location has filled in with sediment. Erosion needs to be controlled from the source.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06223 | Date: 8/8/2019

Inspection Photos



Photo 2. Erosion has been repaired however, this issue can occur again as rilling is beginning to occur.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06223 | Date: 8/8/2019