

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402139757

Date Received:

08/09/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

6 of 7 CAs from the FIR responded to on this Form

6 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10691
Name of Operator: PHOENIX RESOURCES LLC
Address: 5566 S SYCAMORE STREET
City: LITTLETON State: CO Zip: 80120

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Taylor Heffner	281-460-1517	theffner@phxresources.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696200296
Inspection Date: 06/19/2019 FIR Submit Date: 06/19/2019 FIR Status:

Inspected Operator Information:

Company Name: PHOENIX RESOURCES LLC Company Number: 10691
Address: 5566 S SYCAMORE STREET
City: LITTLETON State: CO Zip: 80120

LOCATION - Location ID: 414589

Location Name: MOSHER Number: 1-1H County:
Qtrqr: SESE Sec: 1 Twp: 13S Range: 54W Meridian: 6
Latitude: 38.938372 Longitude: -103.388335

FACILITY - API Number: 05-073-00 Facility ID: 414589

Facility Name: MOSHER Number: 1-1H
Qtrqr: SESE Sec: 1 Twp: 13S Range: 54W Meridian: 6
Latitude: 38.938372 Longitude: -103.388335

CORRECTIVE ACTIONS:

1 CA# 126255

Corrective Action: Immediately control and contain spills/releases, and clean up per Rule 906.a. Contact COGCC EPS staff. Date:

Response: CA COMPLETED Date of Completion: 06/19/2019

Operator Comment: A 1-inch nipple on the wellhead washed out sometime between when our operator visited the site the morning of 6/19/19 and when Mr. Trujillo observed the washout around noon. That evening, our lease operator shut in the well and stopped the leak. Since this occurred, we've installed a coated 1" nipple that is much more durable and has corrected this issue.

COGCC Decision:

COGCC
Representative:

2 CA# 126256

Corrective Action: Comply with Rule 603.f and remove all unused equipment and equipment not needed for production on the location.

Date: 09/21/2018

Response: CA COMPLETED

Date of Completion: 07/12/2019

Operator Comment: All unused equipment and unnecessary equipment has been removed from the location via several large flat beds and semi trucks. This equipment includes wellheads, tubing and casing, heater treaters, a large shipping container, solar panels and brackets, two variable frequency drives, generators, ESP cable spools, poly pipe, and a camper that was used by the previous operator as temporary lodging. Pictures have been captured to document some of this equipment - please see attached.

COGCC Decision: _____

COGCC
Representative:

3 CA# 126257

Corrective Action: Comply with Rule 603.f and properly remove and dispose trash debris.

Date: 06/30/2018

Response: CA COMPLETED

Date of Completion: 07/12/2019

Operator Comment: Debris has been removed, along with weeds and other vegetation that was previously all over location and on the berms. Pictures attached.

COGCC Decision: _____

COGCC
Representative:

4 CA# 126258

Corrective Action: Comply with 210.b.(2) and install signage with an emergency contact phone number at which operator can be reached at all times.

Date: _____

Response: CA COMPLETED

Date of Completion: 07/24/2019

Operator Comment: Phoenix Resources has implemented a system that notifies all employees of any messages left on the emergency line, if not answered - the previous system was ineffective in relaying this information to all employees. Should a message be left on the emergency line, caller will receive a call back within 10 minutes.

COGCC Decision: _____

COGCC
Representative:

5 CA# 126259

Corrective Action: Contact area EPS. Properly treat or dispose of waste and stained soils on location in accordance with Rule 907.e.

Date: 06/01/2018

Response: CA COMPLETED

Date of Completion: 07/21/2019

Operator Comment: Contaminated soil immediately impacted by the leak was cleaned up on the days immediately following the spill and into the following week. Soil sampling bottles were collected and analyzed by Pace Analytical, the results of which were submitted via Form 19 on 7/26/2019.

COGCC Decision: _____

COGCC
Representative:

Corrective Action: Comply with 1002.f and remove containers/buckets/jugs or install BMPsDate: 06/30/2018Response: CA COMPLETEDDate of Completion: 06/28/2019

Operator Comment: All containers, buckets and jugs were removed following the inspection. Should we require additional storage on location to house these items, Phoenix will order a small bin or container to store this in, rather than out in the elements.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions have been completed except for re-vegetation of land no longer required for production operations. As mentioned in the corrective actions and responses tab, we are looking into establishing vegetation with perennial, non-invasive plant cover, now that all extraneous equipment has been removed from location. We will consult with both the surface owner and local county NRCS for the correct seed mix.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Taylor Heffner

Signed: _____

Title: PartnerDate: 8/9/2019 12:42:50 PM**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number Description

402139802	Location Photos and Cleanup Documentation
-----------	-------------------------------------------

Total Attach: 1 Files