

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402140862

Date Received:

08/12/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672

Name of Operator: TIMBER CREEK OPERATING LLC

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Ronald Mack

719-845-2147

ronaldmack@tcenergyllc.com

Edie Fitzgerald

719-859-1396

ediefitzgerald@tcenergyllc.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 689900526

Inspection Date: 04/02/2019

FIR Submit Date: 04/03/2019

FIR Status: _____

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC

Company Number: 10672

Address: 1001 17TH STREET #1000

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 308030

Location Name: APACHE CANYON-634S67W Number: 18NWSW County: LAS ANIMAS

Qtrqtr: NWS Sec: 18 Twp: 34S Range: 67W Meridian: 6
W

Latitude: 37.081346 Longitude: -104.936525

FACILITY - API Number: 05-071- -00 Facility ID: 260247

Facility Name: APACHE CANYON Number: 18-12V

Qtrqtr: NWS Sec: 18 Twp: 34S Range: 67W Meridian: 6
W

Latitude: 37.081346 Longitude: -104.936525

CORRECTIVE ACTIONS:

1 CA# 123822

Corrective Action: Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 05/03/2019

Response: CA COMPLETED

Date of Completion: 08/05/2019

Operator Comment: The cement pad was power washed to remove the oil stains. The impacted soil on the ground was removed and properly disposed of. A pan was placed under the engine skid to contain future leaks.

COGCC Decision:

COGCC Representative:

2 CA# 123823

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 05/03/2019

Response: CA COMPLETED

Date of Completion: 08/05/2019

Operator Comment: The repairs to the access road are complete.

COGCC Decision:

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions have been addressed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed:

Title: SR. Environmental Tech.

Date: 8/12/2019 12:00:13 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

--	--

Total Attach: 0 Files