

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402141973

Date Received:

08/13/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10351

Name of Operator: WAPITI OPERATING LLC

Address: 1310 W SAM HOUSTON PKWY N

City: HOUSTON State: TX Zip: 77043

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Randy Madison

Phone

575-445-6706

Email

rmadison@wapitienergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 689901038

Inspection Date: 07/19/2019

FIR Submit Date: 07/22/2019

FIR Status: _____

Inspected Operator Information:

Company Name: ARP PRODUCTION COMPANY LLC

Company Number: 10471

Address: 425 HOUSTON STREET SUITE 300

City: FORTH WORTH State: TX Zip: 76102

LOCATION - Location ID: 309086

Location Name: VPR C-635S67W Number: 1NESE County: LAS ANIMAS

Qtrqr: NESE Sec: 1 Twp: 35S Range: 67W Meridian: 6

Latitude: 37.025250 Longitude: -104.832530

FACILITY - API Number: 05-071- -00 Facility ID: 287871

Facility Name: VPR C Number: 140

Qtrqr: NESE Sec: 1 Twp: 35S Range: 67W Meridian: 6

Latitude: 37.025250 Longitude: -104.832530

CORRECTIVE ACTIONS:

1 CA# 128380

Corrective Action: Comply with Rule 1003.f.
Control noxious weeds.

Date: 07/11/2019

Response: CA COMPLETED

Date of Completion: 08/13/2019

Operator Comment: The weeds on site were sprayed and are curling. We sprayed the area we have easements for. Road are a 24 foot easement 12 ft. each way from the center of the road. The land owner is responsible for anything beyond that. The pad is anything inside the anchors.

COGCC Decision: _____

COGCC
Representative:

2 CA# 128381

Corrective Action: Comply with the 1003 interim reclamation rules.
Reseed and stabilize the cut slope.

Date: 07/20/2019

Response: CA COMPLETED

Date of Completion: 08/13/2019

Operator Comment: The slope was cat tracked and seeded. Hopefully the seed takes root this fall. Will monitor and watch growth the spring of 2020.

COGCC Decision:

COGCC
Representative:

3 CA# 128382

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 07/20/2019

Response: CA COMPLETED

Date of Completion: 08/13/2019

Operator Comment: Installed rock checks in the ditch on the discharge end of the culvert. Put rock checks on the lease road to the well site to slow the water flow and reduce the erosion.

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Randy Madison

Signed:

Title: HSE Specialist

Date: 8/13/2019 8:59:20 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402142004	Photo of Rock Checks
402142012	Cat Tracked Slope
402142020	Grass Seed Down
402142027	Rock Checks on Lease Road

Total Attach: 4 Files