

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402138298
Date Received:
08/08/2019

FIR RESOLUTION FORM

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10661
Name of Operator: BISON OIL & GAS II LLC
Address: 518 17TH STREET #1800
City: DENVER State: CO Zip: 80202
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Todd Wolff</u>	<u>7206446997</u>	<u>twolff@bisonog.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 696200364
Inspection Date: 07/08/2019 FIR Submit Date: 07/09/2019 FIR Status: _____

Inspected Operator Information:

Company Name: BISON OIL & GAS II LLC Company Number: 10661
Address: 518 17TH STREET #1800
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 452871

Location Name: Castor 8-59 Number: 19 County: _____
Qtrqr: NESE Sec: 19 Twp: 8N Range: 59W Meridian: 6
Latitude: 40.644946 Longitude: -104.011983

FACILITY - API Number: 05-123-00 Facility ID: 452871

Facility Name: Castor 8-59 Number: 19
Qtrqr: NESE Sec: 19 Twp: 8N Range: 59W Meridian: 6
Latitude: 40.644946 Longitude: -104.011983

CORRECTIVE ACTIONS:

1 ☒ CA# 126859

Corrective Action: Install/Repair Stormwater and erosion control BMPs in accordance with 1002.f. Ensure BMPs are installed in accordance with good engineering practice and maintained in proper functioning condition.

Date: 08/09/2019

Response: CA COMPLETED Date of Completion: 07/10/2019

Operator Comment: BMPs were repaired 7/10/2019. Please see attached photos taken 7/10/2019 & 7/23/2019.

COGCC Decision: Approved pending re-inspection

COGCC Representative:	Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules. Based on the photos provided, it does not appear as though BMPs have been installed in accordance with good engineering practices.
-----------------------	---

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ariana Solis

Signed: _____

Title: Regulatory Analyst

Date: 8/8/2019 1:57:51 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402138298	FIR RESOLUTION SUBMITTED
402138320	Corrective Action Pictures

Total Attach: 2 Files