

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402139757

Date Received:

08/09/2019

FIR RESOLUTION FORM

CA Summary:

6 of 7 CAs from the FIR responded to on this Form

6 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10691

Name of Operator: PHOENIX RESOURCES LLC

Address: 5566 S SYCAMORE STREET

City: LITTLETON State: CO Zip: 80120

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Taylor Heffner

281-460-1517

theffner@phxresources.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696200296

Inspection Date: 06/19/2019

FIR Submit Date: 06/19/2019

FIR Status: _____

Inspected Operator Information:

Company Name: PHOENIX RESOURCES LLC

Company Number: 10691

Address: 5566 S SYCAMORE STREET

City: LITTLETON State: CO Zip: 80120

LOCATION - Location ID: 414589

Location Name: MOSHER Number: 1-1H County: _____

Qtrqr: SESE Sec: 1 Twp: 13S Range: 54W Meridian: 6

Latitude: 38.938372 Longitude: -103.388335

FACILITY - API Number: 05-073-00 Facility ID: 414589

Facility Name: MOSHER Number: 1-1H

Qtrqr: SESE Sec: 1 Twp: 13S Range: 54W Meridian: 6

Latitude: 38.938372 Longitude: -103.388335

CORRECTIVE ACTIONS:

1 ☒ CA# 126255

Corrective Action: Immediately control and contain spills/releases, and clean up per Rule 906.a. Contact COGCC EPS staff.

Date: _____

Response: CA COMPLETED

Date of Completion: 06/19/2019

Operator Comment: A 1-inch nipple on the wellhead washed out sometime between when our operator visited the site the morning of 6/19/19 and when Mr. Trujillo observed the washout around noon. That evening, our lease operator shut in the well and stopped the leak. Since this occurred, we've installed a coated 1" nipple that is much more durable and has corrected this issue.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

2 ☒ CA# 126256

Corrective Action: Comply with Rule 603.f and remove all unused equipment and equipment not needed for production on the location.

Date: 09/21/2018

Response: CA COMPLETED

Date of Completion: 07/12/2019

Operator Comment: All unused equipment and unnecessary equipment has been removed from the location via several large flat beds and semi trucks. This equipment includes wellheads, tubing and casing, heater treaters, a large shipping container, solar panels and brackets, two variable frequency drives, generators, ESP cable spools, poly pipe, and a camper that was used by the previous operator as temporary lodging. Pictures have been captured to document some of this equipment - please see attached.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

3 ☒ CA# 126257

Corrective Action: Comply with Rule 603.f and properly remove and dispose trash debris.

Date: 06/30/2018

Response: CA COMPLETED

Date of Completion: 07/12/2019

Operator Comment: Debris has been removed, along with weeds and other vegetation that was previously all over location and on the berms. Pictures attached.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

4 ☐ CA# 126258

Corrective Action: Comply with 210.b.(2) and install signage with an emergency contact phone number at which operator can be reached at all times.

Date: _____

Response: CA COMPLETED

Date of Completion: 07/24/2019

Operator Comment: Phoenix Resources has implemented a system that notifies all employees of any messages left on the emergency line, if not answered - the previous system was ineffective in relaying this information to all employees. Should a message be left on the emergency line, caller will receive a call back within 10 minutes.

COGCC Decision: **Not Approved**

COGCC Representative: COGCC Rule 210.b(2) requires an emergency contact phone number "at which the operator can be reached at all times" on signage.

Any emergency situation resulting with a message having to be left is unsatisfactory and does not comport with the rules.

5 ☒ CA# 126259

Corrective Action: Contact area EPS. Properly treat or dispose of waste and stained soils on location in accordance with Rule 907.e.

Date: 06/01/2018

Response: CA COMPLETED

Date of Completion: 07/21/2019

Operator Comment: Contaminated soil immediately impacted by the leak was cleaned up on the days immediately following the spill and into the following week. Soil sampling bottles were collected and analyzed by Pace Analytical, the results of which were submitted via Form 19 on 7/26/2019.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

7 ☒ CA# 126261

Corrective Action: Comply with 1002.f and remove containers/buckets/jugs or install BMPs

Date: 06/30/2018

Response: CA COMPLETED

Date of Completion: 06/28/2019

Operator Comment: All containers, buckets and jugs were removed following the inspection. Should we require additional storage on location to house these items, Phoenix will order a small bin or container to store this in, rather than out in the elements.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions have been completed except for re-vegetation of land no longer required for production operations. As mentioned in the corrective actions and responses tab, we are looking into establishing vegetation with perennial, non-invasive plant cover, now that all extraneous equipment has been removed from location. We will consult with both the surface owner and local county NRCS for the correct seed mix.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Taylor Heffner

Signed: _____

Title: Partner

Date: 8/9/2019 12:42:50 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402139757	FIR RESOLUTION SUBMITTED
402139802	Location Photos and Cleanup Documentation

Total Attach: 2 Files