

Section 18
T. 6 S., R. 94 W.

BLM

Section 7

Section 18

Section Line

Section 1/16th Line

500' Buffer from
Edge of Disturbance

BLM

NW1/4NW1/4

NE1/4NW1/4

BLM

Existing RWF 21-18 Location

BLM

Section 13

Section 18

SW1/4NW1/4

BLM

SE1/4NW1/4

Existing Access Road

NE $\frac{1}{4}$ NW $\frac{1}{4}$, Section 18, T. 6 S., R. 94 W., 6th P.M.
Footage at Surface: 1181 FNL, 970 FWL
Latitude: 39.528815°
Longitude: 107.934801°
PDOP: 2.6 on GPS Shot #28011
Instrument Operator: J. Kirkpatrick
Date of Measurement: 8/22/17
Measurement Ref. Point: Exist Well RWF 334-7

CURRENT LAND USE

<input type="checkbox"/> CROP LAND	<input checked="" type="checkbox"/> NON-CROP LAND	<input type="checkbox"/> SUBDIVIDED
<input type="checkbox"/> IRRIGATED	<input checked="" type="checkbox"/> RANGELAND	<input type="checkbox"/> INDUSTRIAL
<input type="checkbox"/> DRY LAND	<input type="checkbox"/> TIMBER	<input type="checkbox"/> COMMERCIAL
<input type="checkbox"/> IMPROVED PASTURE	<input type="checkbox"/> RECREATIONAL	<input type="checkbox"/> RESIDENTIAL
<input type="checkbox"/> HAY MEADOW	<input checked="" type="checkbox"/> OTHER (describe): Existing Drill Pad	
<input type="checkbox"/> CRP		

REVISED: 8/13/19

SCALE: 1" = 300'
DATE: 9/20/17
PLAT: 5 of 5
PROJECT: TEP Valley
DFT: cs

Construction Plan Prepared for:



TEP Rocky Mountain LLC

RWF 21-18 Pad - Plat 5
LOCATION

136 East Third Street
Rifle, Colorado 81650
Ph. (970) 625-2720
Fax (970) 625-2773



BOOKCLIFF
Survey Services, Inc.

Visible Improvements to Well Head (ft.)

Description	Building	Building Unit	High Occu. Building	DOAA	Public Road	Above Ground Utility	Railroad	Property Line	School Facility	School Property Line	Child Care Center
Exist. RWF 334-7	>5280	>5280	>5280	>5280	229° 350	185° 3822	>5280	143° 1856	>5280	>5280	>5280
Exist. RWF 434-7	>5280	>5280	>5280	>5280	229° 365	185° 3835	>5280	143° 1860	>5280	>5280	>5280
Exist. RWF 34-7	>5280	>5280	>5280	>5280	229° 379	185° 3847	>5280	143° 1865	>5280	>5280	>5280
Exist. RWF 534-7	>5280	>5280	>5280	>5280	229° 401	185° 3867	>5280	144° 1872	>5280	>5280	>5280
Exist. RWF 433-7	>5280	>5280	>5280	>5280	229° 423	185° 3886	>5280	145° 1879	>5280	>5280	>5280
Exist. RWF 312-18	>5280	>5280	>5280	>5280	229° 348	185° 3826	>5280	143° 1864	>5280	>5280	>5280
Exist. RWF 311-18	>5280	>5280	>5280	>5280	229° 363	185° 3839	>5280	143° 1868	>5280	>5280	>5280
Exist. RWF 421-18	>5280	>5280	>5280	>5280	229° 370	189° 3855	>5280	143° 1871	>5280	>5280	>5280
Exist. RWF 12-18	>5280	>5280	>5280	>5280	229° 378	189° 3861	>5280	144° 1876	>5280	>5280	>5280
Exist. RWF 11-18	>5280	>5280	>5280	>5280	229° 392	189° 3874	>5280	144° 1877	>5280	>5280	>5280
Exist. RWF 512-18	>5280	>5280	>5280	>5280	229° 399	189° 3882	>5280	144° 1881	>5280	>5280	>5280
Exist. RWF 21-18	>5280	>5280	>5280	>5280	229° 406	189° 3888	>5280	144° 1882	>5280	>5280	>5280
Exist. RWF 333-18	>5280	>5280	>5280	>5280	229° 413	189° 3895	>5280	144° 1885	>5280	>5280	>5280
Exist. RWF 321-18	>5280	>5280	>5280	>5280	229° 421	189° 3901	>5280	145° 1887	>5280	>5280	>5280

Production Equipment

Separators	>5280	>5280	>5280	>5280	226° 251	185° 3690	>5280	140° 1764	>5280	>5280	>5280
Tanks	>5280	>5280	>5280	>5280	233° 49	185° 3345	>5280	131° 1491	>5280	>5280	>5280

REVISED: 8/13/19

136 East Third Street
Rifle, Colorado 81650
Ph. (970) 625-2720
Fax (970) 625-2773



SCALE: N/A
DATE: 8/01/19
PLAT: 5a of 5a
PROJECT: TEP Valley
DFT: wk

Construction Plan Prepared for:



TEP Rocky Mountain LLC

RWF 21-18 Pad - Plat 5a
LOCATION TABLE