

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/08/2019

Submitted Date:

08/16/2019

Document Number:

690200050

FIELD INSPECTION FORM

Loc ID 334794 Inspector Name: Heil, John On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: PO BOX 370
City: PARACHUTE State: CO Zip: 81635

Findings:

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Gardner, Mike		mgardner@terraep.com	
Fischer, Alex		alex.fischer@state.co.us	

General Comment:

On August 8, 2019, COGCC Environmental Staff (John Heil) conducted an environmental field inspection of TEP ROCKY MOUNTAIN LLC (TEP operator #96850) Location ID 334794.

COGCC staff observed a cutting trench north of the location measuring approximately 130 feet by 120 feet by 20 feet deep. The cuttings trench had an area of Red / brown / dark brown soil in bottom of the trench measuring approximately 40 feet by 30 feet in size. Mike Gardner with TEP indicated that the dark soil at the base of the trench is drilling mud (See photos).

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____
 Comment:
 Corrective Action: Date: _____
 Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Waste Management:

Type	Management	Condition	GPS (Lat)	(Long)
Drill Cuttings	Pits	Adequate		
Comment	Cuttings trench on location for Federal MV 60-8D pad and the Puckett GV 1-8 pad.			
Corrective Action	Operator shall provide analytical results based on the Operator's CUTTINGS MANAGEMENT PLAN for the drill cuttings that are currently on location. Analytical results should be submitted on a eFrom 4 Sundry under location ID 334794.			Date: 09/16/2019

Spill/Remediation:

Comment:
 Corrective Action: Date: _____

Emission Control Burner (ECB): _____
 Comment:
 Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690200058	20190808 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4911574