

GV 10-34
Location # 323815



Weeds on location.



GV 10-34
Location # 323815



Weeds on location and dead debris.



Tire chain left on location.



GV 10-34
Location # 323815



Weeds on location and dead debris.



Weeds on location and dead debris.



GV 10-34
Location # 323815



Weeds on location and dead debris.



Weeds on location and dead debris.

GV 10-34
Location # 323815



Rills from location into road ditch.



Rills from location into road ditch.

GV 10-34
Location # 323815



Sediment movement and build up in road ditch.



Sediment movement and build up in road ditch.

GV 10-34
Location # 323815



Deadman marker is bent over and not brightly colored.



Deadman marker is bent over and not brightly colored.

GV 10-34
Location # 323815



Cement rebar sticking out of the ground near deadman.



Cement rebar sticking out of the ground near deadman.

GV 10-34
Location # 323815



Pipe and fitting on location.



Pipe and fitting on location.

GV 10-34

Location # 323815



Heated separator is not sitting level.