

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402151482

Date Received:
08/21/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10691

Name of Operator: PHOENIX RESOURCES LLC

Address: 5566 S SYCAMORE STREET

City: LITTLETON State: CO Zip: 80120

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Taylor Heffner

281-460-1517

theffner@phxresources.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 697000053

Inspection Date: 08/20/2019

FIR Submit Date: 08/21/2019

FIR Status: _____

Inspected Operator Information:

Company Name: PHOENIX RESOURCES LLC

Company Number: 10691

Address: 5566 S SYCAMORE STREET

City: LITTLETON State: CO Zip: 80120

LOCATION - Location ID: 414589

Location Name: MOSHER Number: 1-1H County: LINCOLN

Qtrqtr: SESE Sec: 1 Twp: 13S Range: 54W Meridian: 6

Latitude: 38.938370 Longitude: -103.388340

FACILITY - API Number: 05-073- -00 Facility ID: 414591

Facility Name: MOSHER Number: 1-1H

Qtrqtr: SESE Sec: 1 Twp: 13S Range: 54W Meridian: 6

Latitude: 38.938370 Longitude: -103.388340

CORRECTIVE ACTIONS:

1 CA# 129468

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 09/21/2019

Response: CA COMPLETED

Date of Completion: 08/16/2019

Operator Comment: Stuffing box rubbers were the cause of the leak of oil onto the wellhead. On Friday, August 16th, our lease operator replaced these rubbers and cleaned up the soil near the wellhead. Stuffing box rubbers can be variable in how long they will function before requiring replacement. We plan on replacing these on a quarterly basis going forward - if we find that this time is too long, we will adjust accordingly.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Attached picture was taken on August 16th after stuffing box rubbers were replaced.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Taylor Heffner

Signed: _____

Title: Partner

Date: 8/21/2019 10:52:58 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

402151488	Wellhead Photo
-----------	----------------

Total Attach: 1 Files