

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/15/2019

Submitted Date:

08/15/2019

Document Number:

679601327**FIELD INSPECTION FORM**

Loc ID 330137 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections
Kraich, Adam		adam.kraich@state.co.us	

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Produced water BBLS labeling needs to be replaced. See attached photos.		
Corrective Action:	Install sign to comply with Rule 210.e.	Date:	09/15/2019

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:	Debris on south and east end of location. See attached photos.		
Corrective Action:	Comply with Rule 603.f.	Date:	09/15/2019
Type	WEEDS		
Comment:	Weeds around tank battery berm and location. See attached photos.		
Corrective Action:	Comply with Rule 603.f.	Date:	09/15/2019

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type			
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bird Protectors	# 7		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 3		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	

Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4	OTHER	PBV CONCRETE		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	53 BBLS	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares containment wth crude oil tanks			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	4	300 BBLS	STEEL AST		40.361700,-104.826100
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment:	Lined			
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	

Corrective Action:		Date:	
--------------------	--	-------	--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Thursday, August 15, 2019 at approximately 13:20, I, Inspector Brittani Santistevan, conducted an on-site inspection at UPRC /BERNHARDT BATTERY (Noble Energy), at location #: 330137 in WELD COUNTY Colorado.</p> <p>While there, I observed a shut in location.</p> <p>During this inspection, the following possible compliance issues were observed:</p> <p>1. Weeds along most of tank battery berm and other spots on location. Please remove weeds to COMPLY WITH RULE 603.F. (Corrective Action Date: September 15, 2019) See attached photo #3-5.</p> <p>2. Appears to be debris inside tank battery berm and on location from dead tree directly east of location. Please remove to COMPLY WITH RULE 603.F. (Corrective Action Date: September 15, 2019) See attached photos #4-8.</p> <p>3. 3 out of 4 produced water signs have the BBLS sticker peeled off significantly. Please install or repair sign to COMPLY WITH RULE 210.E. (Corrective action Date: September 15, 2019) See attached photos #9,10.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p> <p>Continuing Education Inspection</p>	santistb	08/15/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402146374	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4910777
679601328	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4910760