

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402152564  
Date Received:  
08/22/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10661

Name of Operator: BISON OIL & GAS II LLC

Address: 518 17TH STREET #1800

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Abigail Wenk

720-644-6997

awenk@bisonog.com

Ariana Solis

720-644-6997

asolis@bisonog.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696200568

Inspection Date: 08/08/2019

FIR Submit Date: 08/09/2019

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: BISON OIL & GAS II LLC

Company Number: 10661

Address: 518 17TH STREET #1800

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 455519

Location Name: Boomslang Fed 8-60 Number: 14B County: \_\_\_\_\_

Qtrqr: E2SE Sec: 14 Twp: 8N Range: 60W Meridian: 6

Latitude: 40.659078 Longitude: -104.050458

FACILITY - API Number: 05-123-00 Facility ID: 455519

Facility Name: Boomslang Fed 8-60 Number: 14B

Qtrqr: E2SE Sec: 14 Twp: 8N Range: 60W Meridian: 6

Latitude: 40.659078 Longitude: -104.050458

CORRECTIVE ACTIONS:

1 CA# 129086

Corrective Action: Install or repair required BMPs per Rule 1002.f, and in accordance with good engineering practices.

Date: 08/09/2019

Response: CA COMPLETED

Date of Completion: 08/22/2019

Operator  
Comment:

Please see attached photos. Pad was still undergoing initial construction at the time of inspection.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**2** CA# 129087

Corrective Action: Install or repair required BMPs per Rule 1002.f, and in accordance with good engineering practices.

Date: 08/09/2019

Response: CA COMPLETED

Date of Completion: 08/22/2019

Operator  
Comment: Please see attached photos. Pad was still undergoing initial construction at the time of inspection.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**3** CA# 129088

Corrective Action: Install or repair required BMPs per Rule 1002.f, and in accordance with good engineering practices.

Date: 08/09/2019

Response: CA COMPLETED

Date of Completion: 08/22/2019

Operator  
Comment: Please see attached photos. Pad was still undergoing initial construction at the time of inspection.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**4** CA# 129089

Corrective Action: Install or repair required BMPs per Rule 1002.f, and in accordance with good engineering practices.

Date: 08/09/2019

Response: CA COMPLETED

Date of Completion: 08/22/2019

Operator  
Comment: Please see attached photos. Pad was still undergoing initial construction at the time of inspection.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ariana Solis

Signed: \_\_\_\_\_

Title: Regulatory Analyst

Date: 8/22/2019 11:29:52 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402152592	Corrective Action Photos

Total Attach: 1 Files